

**Javelina Unit (Pad 405) (405H,  
406H, 407H, 408H)  
[fVV2210349229]**

**Weekly Inspection Report  
Q3 2024**

**[4323] CHEVRON USA INC**

**January 02, 2025**

JAVELINA UNIT P405 (405H, 406H, 407H, 408H) Facility ID [fVV2210349229 (Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
7/3/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
7/10/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
7/17/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
7/24/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
7/31/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
8/7/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
8/14/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
8/21/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
8/28/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
9/4/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
9/11/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
9/18/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
9/25/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 415937

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 415937
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
jeffrey.harrison	None	1/2/2025