

JAVELINA UNIT P405 (405H, 406H, 407H, 408H) Facility ID [fVV2210349229 (Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
10/2/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
10/9/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
10/16/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
10/23/2024	good	YES	<1"	X	NO	NO	YES	No issues to report
10/30/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
11/7/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
11/13/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
11/20/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
11/27/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
12/4/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
12/11/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
12/18/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
12/25/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues
12/31/2024	GOOD	YES	<1"	X	NO	NO	YES	No issues

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 418714

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 418714
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	1/10/2025