

Javelina Unit 433 (433H, 434H, 435H) Facility ID - fVV2214553037 (Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
10/2/2024	yes	yes	<1"	no	no	no	yes	no issures to report
10/9/2024	yes	yes	<1"	no	no	no	yes	no issures to report
10/16/2024	yes	yes	<1"	no	no	no	yes	no issures to report
10/23/2024	yes	yes	<1"	no	no	no	yes	no issures to report
10/30/2024	yes	yes	<1"	no	no	no	yes	no issures to report
11/7/2024	yes	yes	<1"	no	no	no	yes	no issures to report
11/13/2024	yes	yes	<1"	no	no	no	yes	no issures to report
11/20/2024	yes	yes	<1"	no	no	no	yes	no issures to report
11/27/2024	yes	yes	<1"	no	no	no	yes	no issures to report
12/4/2024	yes	yes	<1"	no	no	no	yes	no issures to report
12/11/2024	yes	yes	<1"	no	no	no	yes	no issures to report
12/18/2024	yes	yes	<1"	no	no	no	yes	no issures to report
12/25/2024	yes	yes	<1"	no	no	no	yes	no issures to report
12/31/2024	yes	yes	<1"	no	no	no	yes	no issures to report

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 419428

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 419428
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	1/10/2025