

SD 24 13 FED P366 (424H, 425H, 426H, 311H, 312H, 209H, 210H) Facility ID-fJMB2221639957 (Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
9/24/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
9/25/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
9/26/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
9/27/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
9/28/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
9/29/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
9/30/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/1/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/2/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/3/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/4/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/5/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/6/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/7/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/8/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/9/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/10/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/11/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/12/2024	Good	YES	Good	None	None	None	Good	DSR visual daily inspection
10/13/2024	Good	YES	Good	None	None	None	Good	Start Rig Move

SD 24 13 FED P366 (424H, 425H, 426H, 311H, 312H, 209H, 210H) Facility ID-fJMB2221639957 (Weekly inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
10/23/2024	good	OK	good	no	none	no	yes	no issues
10/30/2024	good	OK	good	no	none	no	yes	no issues
11/7/2024	good	OK	good	no	none	no	yes	no issues
11/13/2024	good	OK	good	no	none	no	yes	no issues
11/20/2024	good	OK	good	no	none	no	yes	no issues
11/27/2024	good	OK	good	no	none	no	yes	no issues
12/4/2024	good	OK	good	no	none	no	yes	no issues
12/11/2024	good	OK	good	no	none	no	yes	no issues
12/18/2024	good	OK	good	no	none	no	yes	no issues
12/25/2024	good	OK	good	no	none	no	yes	no issues
12/31/2024	good	OK	good	no	none	no	yes	no issues

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 420550

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 420550
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	1/15/2025