

JAVELINA UNIT Pad 405 (405H, 406H, 407H, 408H) Facility ID - fVV2210349229_(Weekly inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
1/8/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
1/15/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
1/22/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
1/29/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
2/5/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
2/12/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
2/19/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
2/26/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
3/5/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
3/12/2025	GOOD	YES	<1"	<1"	NO	NO	YES	No issues to report
3/19/2025	GOOD	YES	<1"	<1"	NO	NO	YES	3/14 pit closure mobolization
3/26/2025	GOOD	N/A - Mixing for Closure	<1"	<1"	NO	NO	YES	No issues to report
4/2/2025	GOOD	N/A - Mixing for Closure	<1"	<1"	NO	NO	YES	No issues to report
4/9/2025	GOOD	N/A - Mixing for Closure	<1"	<1"	NO	NO	YES	No issues to report

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 451070

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 451070
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	4/11/2025