

JAVELINA UNIT P409 (409H, 410H, 411H, 412H) Facility ID - fVV2210434389 (Weekly inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
4/2/2025	YES	YES	<1"	NO	NO	NO	YES	No Issues
4/9/2025	YES	YES	<1"	NO	NO	NO	YES	No Issues
4/11/2025	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Proceeding pit closure

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 470238

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 470238
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	6/6/2025