

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Chevron U.S.A., Inc.	OGRID 4323
Contact Name Jessica Zemen	Contact Telephone 432-530-9187
Contact email jessicazemen@chevron.com	Incident # (assigned by OCD)
Contact mailing address 6301 Deauville Blvd. Midland, TX 79706	

Location of Release Source

Latitude 32.24052 Longitude -104.00226
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: CB SE 5 Federal Com #011H (Culebra Bluff East)	Site Type: Gas
Date Release Discovered 11/27/2020	API# (if applicable): 30-015-44637

Unit Letter	Section	Township	Range	County
P	05	24S	29E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 89 MCF	Volume Recovered (Mcf) 0 MCF
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Compressor 803 and 805 went down due to a detonation and high suction. The compressor shutdown resulted in a flaring event.

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? N/A
---	---

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Released material was not a liquid therefore the fourth option does not apply.

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Jessica Zemen Title: Lead Environmental Specialist, Field Support

Signature:  Date: 11/28/2020

email: jessicazemen@chevron.com Telephone: 432-530-9187

OCD Only

Received by: _____ Date: _____

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

N/A due to release report is a flare event.

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: _____ Jessica Zemen _____ Title: _____ Lead Environmental Specialist, Field Support _____

Signature: _____ *Jessica K Zemen* _____ Date: _____ 11/28/2020 _____

email: _____ jessiczemen@chevron.com _____ Telephone: _____ 432-530-9187 _____

OCD Only

Received by: _____ Date: _____

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: _____ Date: _____

Printed Name: _____ Title: _____

Incident ID	
District RP	
Facility ID	
Application ID	

3. Time of Event							1. Vented or	2. Calculating Volumetric Release Rate for VRU Releases Incapable of Estimation				3. Gaseous Volumetric Release Rate	
Date of discovery	Time of Discovery or Scheduled Activity Start	Date of start of event or Scheduled Activity Start	Time of Start of Event or Scheduled Activity Start	Date of end of event or Scheduled Activity End	Time of est. or actual end of event or Scheduled Activity End	Duration of Event in Hours	Vent or Flare	Is Volume Metered, Estimated or Otherwise Known?	Daily Production (barrels of oil / day)	Site-specific GOR Available?	Site-specific GOR (scf gas / barrel oil)	Value	Units
11/27/2020	8:00:00	11/27/2020	8:00:00	11/27/2020	8:45:00	0.75	Flare					89	mscf/event

Incident ID	NRM2034451023
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

N/A due to release report is a flare event.

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Jessica Zemen Title: Lead Environmental Specialist, Field Support

Signature: Jessica K Zemen Date: 11/28/2020

email: jessiczemen@chevron.com Telephone: 432-530-9187

OCD Only

Received by: Robert Hamlet Date: 12/11/2020

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Robert Hamlet Date: 12/11/2020

Printed Name: Robert Hamlet Title: Environmental Eng. Tech. III

From: [Hamlet, Robert, EMNRD](#)
To: "Kyndle.Hall@Chevron.com"
Cc: [Bratcher, Mike, EMNRD](#); [Eads, Cristina, EMNRD](#); [CFO Spill, BLM NM](#)
Subject: Closure Approval - Chevron - CB SE 5 Federal Com #11H - (Incident #NRM2034451023)
Date: Friday, December 11, 2020 9:00:00 AM
Attachments: [Closure Approval - Chevron - CB SE 5 Federal Com #11H - \(Incident #NRM2034451023\).pdf](#)

Kyndle,

We have received your closure report and final C-141 for **Incident #NRM2034451023 CB SE 5 Federal Com #11H**, thank you. This closure is approved.

Please let me know if you have any further questions.

Regards,

Robert Hamlet • Environmental Eng. Tech. III
Environmental Bureau
EMNRD - Oil Conservation Division
811 S. First Street | Artesia, NM 88210
505.748.1283 | robert.hamlet@state.nm.us
<http://www.emnrd.state.nm.us/OCD/>



District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 11359

CONDITIONS OF APPROVAL

Operator:	CHEVRON U S A INC	6301 Deauville Blvd	Midland, TX79706	OGRID:	4323	Action Number:	11359	Action Type:	C-141
-----------	-------------------	---------------------	------------------	--------	------	----------------	-------	--------------	-------

OCD Reviewer	Condition
rhamlet	We have received your closure report and final C-141 for Incident #NRM2034451023 CB SE 5 Federal Com #11H, thank you. This closure is approved.