

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2033530478
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

Latitude 32.28412273 Longitude -104.13083298
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: TREBUCHET FEE 23 28 19 WXY #010H	Site Type: Oil & Gas
Date Release Discovered 11/13/2020	API# (if applicable) 30-015-44605

Unit Letter	Section	Township	Range	County
N	19	23S	28E	Eddy

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 45	Volume Recovered (bbls) 45
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

A failed sight glass on the water leg resulted in the release of 45 bbl. of a produced water inside of the lined containment. Repairs were made, and recovery efforts continued as the containment was power-washed to reduce slip/trip/fall risk.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

Released to Imaging: 12/31/2020 10:51:40 AM

Incident ID	NRM2033530478
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Melodie Sanjari Title: Environmental Professional

Signature: Melodie Sanjari Date: 12/23/2020

email: msanjari@marathonoil.com Telephone: 575-988-8753

OCD Only

Received by: Cristina Eads Date: 12/23/2020

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 12/31/2020

Printed Name: Cristina Eads Title: Environmental Specialist

NRM2033530478

Liner Integrity Inspection (Photos Attached)

Date: 12/16/2020 ~4pmFacility: Trebuchet Fee 23 28 19 WXY 20H48 Hour Notification Given On: 12/14/2020* OCD.enviro via email

Responsible party has visually inspected the liner

Y/N

Liner remains intact

Y/N

Liner had the ability to contain the leak in question:

Y/N

Notes:

powerwashed 12/15
no liner rips/tears
no overspray or failures on containment itself.
some windblown sand.

Company Representative(s)

Melodie Sanjari



TREBUCHET FEE 23 28 19 WXY #010H Photo Log

NRM2033530478




TREBUCHET FEE 23 28 19 WXY #010H Photo Log

NRM2033530478



TREBUCHET FEE 23 28 19 WXY #010H Photo Log

NRM2033530478



TREBUCHET FEE 23 28 19 WXY #010H Photo Log

NRM2033530478



TREBUCHET FEE 23 28 19 WXY #010H Photo Log

NRM2033530478



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 13020

CONDITIONS OF APPROVAL

Operator: MARATHON OIL PERMIAN LLC Permian Regulatory Team	5555 San Felipe St. Houston, TX77056	OGRID: 372098	Action Number: 13020	Action Type: C-141
OCD Reviewer ceads	Condition None			