

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2102551487
District RP	
Facility ID	30-015-43999
Application ID	

Release Notification

Responsible Party

Responsible Party: Spur Energy Partners LLC	OGRID: 328947
Contact Name: Kenny Kidd	Contact Telephone: 575-616-5400
Contact email: kkidd@spurepllc.com	Incident # (assigned by OCD): NAPP2102551487
Contact mailing address: 920 Memorial City Way Suite 1000 Houston, TX 77024	

Location of Release Source

Latitude 32.601809 Longitude -104.4572301 (location of source)
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Bone Yard 11 Fee 16H	Site Type: Oil Production
Date Release Discovered: 01/23/2021	API# (if applicable) 30-015-43999

Unit Letter	Section	Township	Range	County
K	02	20S	25E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 40bbls	Volume Recovered (bbls) 35bbls
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:
A 6" suction line between the water tanks developed a hole creating a leak.
The Spill Calculation is as follows: $90' \times 30' \times 0.83/5.62 = 39.875$ bbls

Oil Conservation Division

Incident ID	NAPP2102551487
District RP	
Facility ID	30-015-43999
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? The volume of the spill was greater than 5bbl
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Immediate notice was provided to the NMOCD by Kenny Kidd with Spur Energy to: Mike Bratcher, Robert Hamlet, Jim Griswold	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Rebecca Pons</u> Title: <u>Project Manager</u>
Signature: <u>Rebecca Pons</u> Date: <u>01/27/2021</u>
email: <u>Rpons@talonlpe.com</u> Telephone: <u>575-441-0980</u>
<u>OCD Only</u> Received by: _____ Date: _____

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 15841

CONDITIONS OF APPROVAL

Operator: TALON LPE 408 W Texas Artesia, NM88210	OGRID: 329944	Action Number: 15841	Action Type: C-141
OCD Reviewer marcus	Condition None		