



Certificate of Analysis

Number: 6030-21050225-001A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Jerry Mathews
 Spur Energy
 1012 Marquez Place, Suite 106b
 Santa Fe, NM 87505

May 26, 2021

Station Name: Welch A 28 State CTB Flare
 Station Number: 79410130
 Station Location: Spur
 Sample Point: Meter Run
 Type of Sample: Spot-Cylinder
 Heat Trace Used: N/A
 Sampling Method: Fill and Purge
 Sampling Company: SPL
 Analyzed: 05/26/2021 07:28:51 by KNF

Sampled By: Mike West
 Sample Of: Gas Spot
 Sample Date: 05/21/2021
 Sample Conditions: 18 psig, @ 95.5 °F Ambient: 91 °F
 Effective Date: 05/21/2021
 Method: GPA 2286
 Cylinder No: 5030-01628
 Instrument: 6030_GC2 (Agilent GC-7890B)
 Last Inst. Cal.: 05/18/2021 10:19 AM

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia		
Hydrogen Sulfide	0.000	0.40000	0.552		GPM TOTAL C2+	8.881
Nitrogen	1.714	1.70600	1.935		GPM TOTAL C3+	4.816
Methane	66.654	66.33600	43.095		GPM TOTAL iC5+	1.078
Carbon Dioxide	0.738	0.73400	1.308			
Ethane	15.201	15.12800	18.420	4.065		
Propane	8.809	8.76700	15.655	2.427		
Iso-butane	1.206	1.20000	2.824	0.395		
n-Butane	2.907	2.89300	6.809	0.916		
Iso-pentane	0.717	0.71400	2.086	0.263		
n-Pentane	0.712	0.70900	2.071	0.259		
Hexanes Plus	1.420	1.41300	5.245	0.556		
	100.078	100.00000	100.000	8.881		

Calculated Physical Properties

Relative Density Real Gas	Total	C6+
	0.8564	3.1508
Calculated Molecular Weight	24.69	91.25
Compressibility Factor	0.9950	

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.73 psia & 60°F

Real Gas Dry BTU	1430	4856
Water Sat. Gas Base BTU	1405	4772
Ideal, Gross HV - Dry at 14.73 psia	1423.0	4856.4
Ideal, Gross HV - Wet	1398.2	0.000

Comments: H₂S Field Content 0.4 %
 Mcf/day 549.8

Report generated by: Krystle Fitzwater

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

ProdView®**FlareV1**

Printed: 6/21/2021 4:25 PM

Date: 6/20/2021 to 6/20/2021

Unit Battery	Alloc Flare Gas (MCF)
LAKEWOOD NORTH TANK BATTERY	2,790.00
LAKEWOOD SOUTH TANK BATTERY	1,851.00
SHELBY 23 TANK BATTERY	1,839.00
ROSS RANCH 09.13.14 BATTERY	1,389.00
OSAGE BOYD 15 FED 09.12.13.14 TANK BATTERY	1,332.00
DORAMI 33 FEDERAL COM 2H.4H.9H TANK BATTERY	885.00
HUBER 10,11,12 FEDERAL OIL TANK BATTERY	704.00
Ivar the Boneless Fed 11H - Battery	88.00
WELCH A 28 10H.20H.50H CTB	74.00

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 34589

QUESTIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947 Action Number: 34589 Action Type: [C-129] Venting and/or Flaring (C-129)
---	---

QUESTIONS**Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting or flaring caused by an emergency or malfunction	No
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a notification of a major venting or flaring	Yes, answer to "eight hours or more" suggests this is at least a minor event.
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19.13.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	No
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

Unregistered Facility Site

Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (##) yet.

Facility or Site Name	Weich A 28 State Com 10H.20H.50H Tank Battery
Facility Type	Tank Battery - (TB)

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	66
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting or flaring was discovered or commenced	06/22/2021
Time venting or flaring was discovered or commenced	12:00 AM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	06/23/2021
Time venting or flaring was terminated	12:00 AM
Total duration of venting or flaring in hours, if venting or flaring has terminated	24
Longest duration of cumulative hours within any 24-hour period during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Other (Specify) Natural Gas Flared Spilled: 0 Mcf Recovered: 0 Mcf Lost: 0 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	74 mcf/day flared. "Was there or will there be at least 50 mcf of natural gas vented or flared during this event" doesn't seem to work when marked yes. Yes, there was over 50 mcf flared during this event.
Is this a gas only submission (i.e. only Mcf values reported)	More volume information must be supplied to determine if this will be treated as a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	3rd party tie in delays.
Steps taken to limit the duration and magnitude of venting or flaring	Tie in by 6/18 EOW.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Tie in by 6/18 EOW.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 34589

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 34589
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	7/1/2021