GAS VOLUME STATEMENT

Spur Energy

May, 2021

Meter #: 79410102

Name: Ross Ranch HP Flare

Closed Data

Artesia-East

Pressure Base: 14.730 psia Temperature Base: 60.00 °F **HV Cond:** Meter Type: EFM Contract Hr.: Midnight Status: In Service WV Technique: WV Method: CO2 N2 H20 H2S C1 C2 C3 I-C4 N-C4 I-C5 N-C5 C6+ He 0.492 3.028 2.516 2.6586 0.000 64.576 8.241 1.046 2.344 0.526 0.000 0.000 14.108 0.467

Tube I.D.	Interval	Tap Location	Tap Type	Atmos. Pressure	Calc. Method	Fpv Method
4.026 in.	1 Hour	Upstream	Flange	12.980 psi	AGA3-1992	AGA8-Detail

Day	Differential (In. H2O)	Pressure (psia)	Temperature	Hours Flow	Relative Density	Plate (inches)	Volume (Mcf)	Heating Value (Btu/scf)	Energy (MMBtu)	Edited
1	12.56	(psia) 38.74	(° F) 75.47	24.00	0.8116	, ,	906.79	1293.10	, ,	No
2	12.56	38.74	75.47 79.95	24.00	0.8116	2.625 2.625	914.26	1293.10	1,172.57 1,182.23	No
3	13.27	38.26	79.95 75.91	24.00	0.8116	2.625	925.30	1293.10	1,196.50	No
4	13.23	38.51	72.08	24.00	0.8116	2.625	930.62	1293.10	1,203.39	No
5	13.68	38.43	79.63	24.00	0.8116	2.625	938.13	1293.10	1,213.10	No
6	13.66	38.39	79.28	24.00	0.8116	2.625	937.32	1293.10	1,212.05	No
7	14.22	38.24	84.86	24.00	0.8116	2.625	949.18	1293.10	1,227.39	No
8	14.23	38.08	83.57	24.00	0.8116	2.625	948.94	1293.10	1,227.08	No
9	10.53	37.80	82.42	24.00	0.8116	2.625	749.92	1293.10	969.72	No
10	10.74	37.87	78.63	24.00	0.8116	2.625	827.07	1293.10	1,069.49	No
11	10.83	37.97	74.14	24.00	0.8116	2.625	822.66	1293.10	1,063.78	No
12	14.64	38.30	68.19	24.00	0.8116	2.625	916.75	1293.10	1,185.46	No
13	21.77	38.43	74.94	24.00	0.8116	2.625	1,160.78	1293.10	1,501.00	No
14	19.40	38.18	79.90	24.00	0.8116	2.625	1,109.54	1293.10	1,434.75	No
15	20.17	38.01	79.70	24.00	0.8116	2.625	1,129.64	1293.10	1,460.73	No
16	21.23	37.96	81.87	24.00	0.8116	2.625	1,155.34	1293.10	1,493.97	No
17	21.66	37.87	81.68	24.00	0.8116	2.625	1,165.64	1293.10	1,507.29	No
18	21.95	37.86	79.61	24.00	0.8116	2.625	1,175.54	1293.10	1,520.09	No
19	22.52	37.84	82.86	24.00	0.8116	2.625	1,186.45	1293.10	1,534.20	No
20	22.98	37.91	84.92	24.00	0.8116	2.625	1,197.39	1293.10	1,548.34	No
21	23.28	38.12	84.30	24.00	0.8116	2.625	1,209.13	1293.10	1,563.52	No
22	23.19	38.15	79.04	24.00	0.8116	2.625	1,213.21	1293.10	1,568.80	No
23	23.73	38.19	83.78	24.00	0.8116	2.625	1,222.06	1293.10	1,580.24	No
24	24.45	38.18	85.19	24.00	0.8116	2.625	1,238.32	1293.10	1,601.27	No
25	25.14	38.19	85.76	24.00	0.8116	2.625	1,254.95	1293.10	1,622.77	No
26	25.18	38.20	84.41	24.00	0.8116	2.625	1,257.88	1293.10	1,626.56	No
27	25.73	38.23	85.76	24.00	0.8116	2.625	1,270.00	1293.10	1,642.24	No
28	25.77	38.28	84.14	24.00	0.8116	2.625	1,273.65	1293.10	1,646.96	No
29	24.40	38.28	80.61	24.00	0.8116	2.625	1,228.95	1293.10	1,589.16	No
30	26.00	38.36	80.20	24.00	0.8116	2.625	1,285.05	1293.10	1,661.70	No
31	26.11	38.46	74.99	24.00	0.8116	2.625	1,296.07	1293.10	1,675.94	No
TOTAL	20.14	38.18	80.54	744.00	0.8116		33,796.53		43,702.29	

Name of well or facility	Lat	Long	Daily Volume of Flared Natural Gas (MCF/D)	Commencement	Duration	Proposed Remedy
SHELBY 23 TANK BATTERY	32.636495	-104.449015	1609 MCF/D	7/30/2021	Continuous	ACO Requested
ROSS RANCH 09.13.14 BATTERY	32.636187	-104.47781	1431 MCF/D	7/30/2021	Continuous	ACO Requested
OSAGE BOYD 15 FED 09.12.13.14 TANK BATTERY	32.652839	-104.478905	1157 MCF/D	7/30/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM NORTH BATTERY	32.625808	-104.469155	2610 MCF/D	7/30/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM SOUTH BATTERY	32.608649	-104.479201	1853 MCF/D	7/30/2021	Continuous	ACO Requested
DORAMI 33 FEDERAL COM 2H.4H.9H TANK BATTERY	32.614416	-104.478493	636 MCF/D	7/30/2021	Continuous	ACO Requested
HUBER 10, 11, 12 FEDERAL OIL TANK BATTERY	32.610648	-104.472851	250 MCF/D	7/30/2021	Continuous	ACO Requested
MORRIS BOYD TANK BATTERY	32.6250267	-104.4488373	50 MCF/D	7/30/2021	Continuous	Gas Rerouted
PERE MARQUETTE 18 FEDERAL 1 TANK BATTERY	32.8410149	-104.1203232	381 MCF/D	7/30/2021	Continuous	Gas Rerouted

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 41182

QUESTIONS

ı	Operator:	OGRID:
ı	Spur Energy Partners LLC	328947
ı	9655 Katy Freeway	Action Number:
ı	Houston, TX 77024	41182
ı		Action Type:
ı		[C-129] Venting and/or Flaring (C-129)

QUESTIONS

Determination of Reporting Requirements			
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.			
Was or is this venting or flaring caused by an emergency or malfunction	No		
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes		
Is this considered a submission for a notification of a major venting or flaring	Yes, answer to "eight hours or more" suggests this is at least a minor event.		
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during vi	nting or flaring that is or may be a major or minor release under		
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	No		
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No		

Unregistered Facility Site	
Please provide the facility details, if the venting or flaring occurred or is occuring at a facility to	that does not have an Facility ID (f#) yet.
Facility or Site Name	ROSS RANCH 09.13.14 BATTERY
Facility Type	Tank Battery - (TB)

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas			
Please provide the mole percent for the percentage questions in this group.			
Methane (CH4) percentage	65		
Nitrogen (N2) percentage, if greater than one percent	3		
Hydrogen Sulfide (H2S) PPM, rounded up	26,586		
Carbon Dioxide (C02) percentage, if greater than one percent	3		
Oxygen (02) percentage, if greater than one percent	0		
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.			
Methane (CH4) percentage quality requirement	Not answered.		
Nitrogen (N2) percentage quality requirement	Not answered.		
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.		
Carbon Dioxide (C02) percentage quality requirement	Not answered.		
Oxygen (02) percentage quality requirement	Not answered.		

Date(s) and Time(s)		
Date venting or flaring was discovered or commenced	07/30/2021	
Time venting or flaring was discovered or commenced	12:00 AM	
Is the venting or flaring event complete	Yes	
Date venting or flaring was terminated	07/31/2021	
Time venting or flaring was terminated	12:00 AM	
Total duration of venting or flaring in hours, if venting or flaring has terminated	24	
Longest duration of cumulative hours within any 24-hour period during this event	24	

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Other (Specify) Natural Gas Flared Spilled: 0 Mcf Recovered: 0 Mcf Lost: 0 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	1431 mcf/day flared. "Was there or will there be at least 50 mcf of natural gas vented or flared during this event" doesn't seem to work when marked yes. Yes, there was over 50 mcf flared during this event.
Is this a gas only submission (i.e. only Mcf values reported)	More volume information must be supplied to determine if this will be treated as a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	3rd party take away refusal due to capacity restraints.
Steps taken to limit the duration and magnitude of venting or flaring	Executed contract with midstream company to gather gas by 12/1/2021.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Executed contract with midstream company to gather gas by 12/1/2021.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 41182

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	41182
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	8/11/2021