



Athens, TX (903) 677-0700 . Beeville, TX (361) 354-5200 . Midland, TX (432) 704-5351

GAS ANALYSIS REPORT

LAB REPORT NUMBER: 6419 - 01252021

PHYSICAL CONSTANTS PER GPA 2145-16

CUSTOMER:	BTA OIL PRODUCERS LLC	DATE ANALYZED:	1/26/2021
STATION:	80939924	DATE ON:	1/25/2021
PRODUCER:		DATE OFF:	
LEASE:	SOUTH RIDGE 2H	SAMPLED BY	Landon Johnson
EFFECTIVE DATE:	1/1/2021		

<u>COMPONENT:</u>	<u>MOLE %</u>	<u>GPM</u>	<u>WT. %</u>
H2S	0.009		0.000
OXYGEN	0.003		0.004
NITROGEN	1.598		1.901
CARBON DIOXIDE	2.417		4.518
METHANE	72.088		49.119
ETHANE	11.295	3.017	14.425
PROPANE	6.693	1.842	12.536
I-BUTANE	0.954	0.312	2.355
N-BUTANE	2.260	0.712	5.579
I-PENTANE	0.601	0.220	1.841
N-PENTANE	0.585	0.212	1.792
HEXANE PLUS	<u>1.498</u>	<u>0.649</u>	<u>5.929</u>
TOTAL	100.000	6.962	100.000

(ALL VALUES CALCULATED @ 14.65 PSIA + 60 DEG. F)

REAL GRAVITY	0.8162	BTU WET BASIS	1304.54
MOL WT.	23.544	BTU DRY BASIS	1327.20
H2S PPM:	90.000	CO2 %:	

SAMPLE TYPE	SPOT	SAMPLE PRESS:	104
CYLINDER NO	6419	SAMPLE TEMP:	91
NOTES		COUNTY/STATE:	

1/26/2021

South Ridge CTB

7/31/2021

Gas Volumes are reported 1 day late

CHART		TABLE	
Property	Yesterday	DOWNLOAD CSV	Date Range
			30 days
Sta...	07/10/2021 10:02 AM		
End	08/09/2021 10:02 AM		
TimeStamp		Yesterday (mcf)	
8/1/21 11:57 PM		1,096	
8/1/21 10:57 PM		1,096	
8/1/21 9:57 PM		1,096	
8/1/21 8:57 PM		1,096	
8/1/21 7:57 PM		1,096	
8/1/21 6:57 PM		1,096	
8/1/21 5:57 PM		1,096	
8/1/21 4:57 PM		1,096	
8/1/21 3:57 PM		1,096	
8/1/21 2:57 PM		1,096	
8/1/21 1:57 PM		1,096	
8/1/21 12:56 PM		1,096	
8/1/21 12:55 PM		601	
8/1/21 11:57 AM		601	

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 41194

QUESTIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 41194
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting or flaring caused by an emergency or malfunction	No
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a notification of a major venting or flaring	Yes, major venting or flaring of natural gas.
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19.13.297 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

Unregistered Facility Site

Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (##) yet.

Facility or Site Name	South Ridge CTB
Facility Type	Flare Stack - (FS)

Equipment Involved

Primary Equipment Involved	Gas Plant
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	72
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	90
Carbon Dioxide (CO2) percentage, if greater than one percent	2
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting or flaring was discovered or commenced	07/31/2021
Time venting or flaring was discovered or commenced	12:00 AM
Is the venting or flaring event complete	No
Date venting or flaring was terminated	07/31/2021
Time venting or flaring was terminated	11:59 PM
Total duration of venting or flaring in hours, if venting or flaring has terminated	24
Longest duration of cumulative hours within any 24-hour period during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Gas Plant Natural Gas Flared Spilled: 1,096 Mcf Recovered: 0 Mcf Lost: 1,096 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting or flaring a result of downstream activity	Yes
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	High Line Pressure
Steps taken to limit the duration and magnitude of venting or flaring	Battery Redesign
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Battery Redesign

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 41194

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 41194
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	8/11/2021