

Certificate of Analysis

Number: 6030-21060083-004A

Artesia Laboratory 200 E Main St. Artesia, NM 88210 Phone 575-746-3481

June 09, 2021

Spur Energy

1012 Marquez Place, Suite 106b Santa Fe, NM 87505

Station Name: Dorami CTB Sampled By: Donavan Miller
Station Number: N/A Sample Of: Gas Spot
Station Location: Spur Sample Date: 06/07/2021 09:33

Sample Point: Meter run Sample Conditions: 46.8 psig, @ 109 °F Ambient: 81 °F

Type of Sample: Spot-Cylinder Effective Date: 06/07/2021 09:33

Heat Trace Used: N/A Method: GPA-2261M

Sampling Method: Fill and Purge Cylinder No: 1111-002600

Sampling Method: Fill and Purge Cylinder No: 1111-002600
Sampling Company: SPL Instrument: 70104124 (Inficon GC-MicroFusion)

Analyzed: 06/08/2021 13:05:55 by KNF Last Inst. Cal.: 05/18/2021 0:00 AM

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia
Nitrogen	2.296	2.71551	3.188	
Carbon Dioxide	1.833	2.16808	3.998	
Methane	60.705	71.78982	48.261	
Ethane	10.663	12.60992	15.889	3.387
Propane	3.052	3.60920	6.669	0.999
Iso-Butane	0.889	1.05169	2.562	0.346
n-Butane	2.109	2.49353	6.073	0.790
Iso-Pentane	0.686	0.81103	2.452	0.298
n-Pentane	0.632	0.74753	2.260	0.272
Hexanes	0.518	0.61200	2.210	0.253
Heptanes	0.581	0.68745	2.887	0.319
Octanes	0.338	0.39913	1.911	0.205
Nonanes Plus	0.258	0.30511	1.640	0.172
	84.560	100.00000	100.000	7.041
Calculated Physical	Properties	Tota	I	C9+
Calculated Molecular \	Weight	23.86	6	128.26
Compressibility Factor		0.9954	ļ	
Relative Density Real		0.8274	ļ	4.4283
GPA 2172 Calculation	===			
Calculated Gross BTU per ft ³ @ 14.73 psia & 60°F				
Real Gas Dry BTU		1339.5	5	7012.5
Water Sat. Gas Base I	BTU	1316.7	7	6890.4
Ideal, Gross HV - Dry	at 14.73 psia	1333.3		7012.5
Ideal, Gross HV - Wet		1310.1		6890.4

Report generated by: Krystle Fitzwater

The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

Quality Assurance:

Received by OCD: 8/25/2021 1:49:54 PM

Name of well or facility	Lat	Long	Daily Volume of Flared Natural Gas (MCF/D)	Commencement	Duration	Proposed Remedy
SHELBY 23 TANK BATTERY	32.636495	-104.449015	1339 MCF/D	8/16/2021	Continuous	ACO Requested
ROSS RANCH 09.13.14 BATTERY	32.636187	-104.47781	1462 MCF/D	8/16/2021	Continuous	ACO Requested
OSAGE BOYD 15 FED 09.12.13.14 TANK BATTERY	32.652839	-104.478905	878 MCF/D	8/16/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM NORTH BATTERY	32.625808	-104.469155	2952 MCF/D	8/16/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM SOUTH BATTERY	32.608649	-104.479201	1633 MCF/D	8/16/2021	Continuous	ACO Requested
DORAMI 33 FEDERAL COM 2H.4H.9H TANK BATTERY	32.614416	-104.478493	770 MCF/D	8/16/2021	Continuous	ACO Requested
HUBER 10, 11, 12 FEDERAL OIL TANK BATTERY	32.610648	-104.472851	783 MCF/D	8/16/2021	Continuous	ACO Requested

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 44413

QUESTIONS

OGRID:

328947	
Action Number:	
44413	
Action Type: [C-129] Venting and/or Flaring (C-129)	
·	
olve these issues before continuing with the rest of the questions.	
Not answered.	
[fAPP2122833451] Dorami 33 Federal Com 2H.4H.9H Tank Battery	
rs and may provide addional guidance.	
No	
Yes	
Yes, major venting and/or flaring of natural gas.	
ng venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Yes	
ic No	
No	
Not answered.	
9	

Representative Compositional Analysis of Vented or Flared Natural Gas				
Please provide the mole percent for the percentage questions in this group.				
Methane (CH4) percentage	72			
Nitrogen (N2) percentage, if greater than one percent	3			
Hydrogen Sulfide (H2S) PPM, rounded up	0			
Carbon Dioxide (C02) percentage, if greater than one percent	2			
Oxygen (02) percentage, if greater than one percent	0			
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.				
Methane (CH4) percentage quality requirement	Not answered.			
Nitrogen (N2) percentage quality requirement	Not answered.			
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.			
Carbon Dioxide (C02) percentage quality requirement	Not answered.			
Oxygen (02) percentage quality requirement	Not answered.			

Date(s) and Time(s)			
Date venting and/or flaring was discovered or commenced	08/16/2021		
Time venting and/or flaring was discovered or commenced	12:00 AM		
Time venting and/or flaring was terminated	12:00 AM		
Cumulative hours during this event	24		

Measured or Estimated Volume of Vented or Flared Natural Gas		
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Sub-Ventod (Wor) Botalie		

Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Other (Specify) Natural Gas Flared Released: 770 Mcf Recovered: 0 Mcf Lost: 770 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity		
Was or is this venting and/or flaring a result of downstream activity	Not answered.	
Date notified of downstream activity requiring this venting and/or flaring	Not answered.	
Time notified of downstream activity requiring this venting and/or flaring	Not answered.	

Steps and Actions to Prevent Waste			
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True		
Please explain reason for why this event was beyond your operator's control	3rd party take away refusal due to capacity restraints.		
Steps taken to limit the duration and magnitude of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.		
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 44413

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	44413
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
schapman0	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/25/2021