6/10/2021 3:44 PM

Analysis Certificate Report Lucid Energy Group-PURCHASER

BROCK A BOWMAN

3100 McKinnon St #800 Dallas, TX 75201

Analysis ID:	14743	Alternate	ID:	Use Cor	ntract Values: No
Name	Gipple CDP	Company Name: Lucid Energy Group			
Effective Date:	10/01/2020 08:00	Saturated HV:	1317.8	Sample Date:	10/07/2020
Valid Thru Date	12/31/2078 00:00	As Del. HV:	1331.4	Sample ID:	6030-20100094- 006A
Fixed Edit Date	: 01/01/1900 00:00	Dry HV:	1339.7	Sample Type:	Spot
Last Update:	10/23/2020 14:56	Measured HV:	1339.7	Sample Pressure Base:	14.730
Data Acqusition	n: File Transfer from Lab		1506.0	•	103.0
Data Source:	Lab Analysis	Water Content:	0.7	Sample Pressure:	165.0
Real Relative D	ensity: 0.7913	Status:	Active	Lab Code:	
Component	<u> </u>	GPM	Dry Gravity		
Methane	71.9231		Saturated G	Gravity	
Ethane	12.9015	3.4648			
Propane	7.1740	1.9847			
I Butane	0.8705	0.2861			
N Butane	2.2867	0.7239			
I Pentane	0.5375	0.1974			
N Pentane	0.5432	0.1977			
Hexanes +	0.7852	0.3441			
Nitrogen	1.4591				
CO2	0.7996				
Oxygen	0.0000				
H2O	0.6600				
СО	0.0000				
H2S	0.0596				
Hydrogen	0.0000				
Helium	0.0000				
Argon	0.0000				
Total	100.0000	7.1987			

Sample Comments:

Configuration Comments:

Flaring Summary

battery	8/22/2021
Gipple Fed Com Tank Battery	179.90
Grand total	179.90

date

Data table:
flare_report_data (2)
Colors:
All values

batt

Sum(TOTAL FLARE (HP + LP))

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 46974

Q	UESTIONS	
Operator:		OGRID: 273043
TAP ROCK OPERATING, LLC 523 Park Point Drive		372043 Action Number:
Golden, CO 80401		46974
		Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve	these issues before continuing wi	th the rest of the questions.
Incident Well	[30-025-46668] GIPPLE FE	DERAL COM #114H
Incident Facility	Not answered.	
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers at	nd may provide addional quidance	
Was or is this venting and/or flaring caused by an emergency or malfunction	Yes	
Did or will this venting and/or flaring caused by an emergency of manufaction		
any 24-hour period from a single event	No	
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or	flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v	enting and/or flaring that is or may	y be a major or minor release under 19.15.29.7 NMAC.
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes	
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.	1	
Methane (CH4) percentage	72	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	1	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required spec	ifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	
Date(s) and Time(s)		
Date venting and/or flaring was discovered or commenced	08/21/2021	
Time venting and/or flaring was discovered or commenced	06:00 AM	
Time venting and/or flaring was terminated	06:00 AM	
Cumulative hours during this event	2	
Measured or Estimated Volume of Vented or Flared Natural Gas		

Not answered.

Natural Gas Vented (Mcf) Details

Natural Gas Flared (Mcf) Details	Cause: Midstream Emergency Maintenance Gas Compressor Station Natural Gas Flared Released: 179 Mcf Recovered: 0 Mcf Lost: 179 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity		
Was or is this venting and/or flaring a result of downstream activity	No	
Was notification of downstream activity received by you or your operator	Not answered.	
Downstream OGRID that should have notified you or your operator	Not answered.	
Date notified of downstream activity requiring this venting and/or flaring	Not answered.	
Time notified of downstream activity requiring this venting and/or flaring	Not answered.	

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	Lucid received a slug of fluid at their Red Hills plant so they had to curtail volumes, forcing us to flare. Due to this Tap Rock flare numbers spiked larger than regulated volumes. Once Lucid can solve their issue, Tap Rock should see normal operations. No timetable has been given to fix this issue.
Steps taken to limit the duration and magnitude of venting and/or flaring	Lucid received a slug of fluid at their Red Hills plant so they had to curtail volumes, forcing us to flare. Due to this Tap Rock flare numbers spiked larger than regulated volumes. Once Lucid can solve their issue, Tap Rock should see normal operations. No timetable has been given to fix this issue.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Lucid received a slug of fluid at their Red Hills plant so they had to curtail volumes, forcing us to flare. Due to this Tap Rock flare numbers spiked larger than regulated volumes. Once Lucid can solve their issue, Tap Rock should see normal operations. No timetable has been given to fix this issue.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 46974

CONDITIONS

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	46974
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
bramsey	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	9/8/2021