<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural** Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2015756964
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Bob Hall	Contact Telephone: 432-682-3753
Contact email: bhall@btaoil.com	Incident # (assigned by OCD) NRM2015756964
Contact mailing address: 104 S. Pecos St., Midland, TX 79701	

Location of Release Source

Latitude: 32.05101° Longitude: -103.61744°

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Mesa B 8115 JVP #5H Produced Water Line		Site Type: Flowline				
Date Release Discovered: 5/18/2020 API# (if applicable) Nearest well: Mesa B #5H Al		st well: Mesa B #5H API #30-025-42128				
Unit Letter	Section	Township	Range		County	
М	7	26S	33E	33E Lea		<u> </u>

	1				
Surface Owner	r: State	▼ Federal □ Ti	rihal 🔲 Private ()	Vame.	1

Nature and Volume of Release

Material	(s) Released (Select all that apply and attach calculations or specific	ustification for the volumes provided below)	
Crude Oil	Volume Released (bbls) 1 BBL	Volume Recovered (bbls) 0 BBL	
☐ Produced Water	Volume Released (bbls) 276 BBL	Volume Recovered (bbls) 0 BBL (corrected)	
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	⊠ Yes □ No	
Condensate	Volume Released (bbls)	Volume Recovered (bbls)	
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)	
Cause of Release			

A split in the produced water flowline released produced water into several gullies and a pipeline ROW.

The reported volume was determined by measuring the area of the "wetted" area from a drone picture. Then, using analytical data to identify an impacted depth and an estimated porosity, a calculated volume of the release was estimated to be 276 BBL of unrecovered produced water, plus negligible oil.

(9/21/2021) Correction made above to show there was no volume of Produced Water recovered as indicated originally in the statement immediately above and on the original Spill Calculation Spreadsheet.

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NRM2015756964
District RP	
Facility ID	
Application ID	V.

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?				
19.15.29.7(A) NMAC?	The spill volume was greater than 25 BBL, which the NMOCD Rules define as a major				
⊠ Yes □ No	release.				
☑ res ☐ No					
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?				
	not believed to be greater than 25 BBL. However, evaluation of analytical data is being eater volume of a release.				
Initial Response					
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury				
☐ The source of the rele	ease has been stopped.				
☐ The impacted area ha	s been secured to protect human health and the environment.				
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.				
All free liquids and re	ecoverable materials have been removed and managed appropriately.				
If all the actions described	d above have not been undertaken, explain why:				
Per 19 15 29 8 B (4) NM	AC the responsible party may commence remediation immediately after discovery of a release. If remediation				
has begun, please attach	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and				
public health or the environs	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have				
	ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws				
and/or regulations.					
Printed Name: Bob Hal	Title: Environmental Manager				
20	.				
Signature:	Date: Correction 9/21/2021				
email: bhall@btaoil.c	om Telephone: 432-682-3753				
OCD Only					
Received by:	Ramona Marcus Date: 9/21/2021				

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 50586

CONDITIONS

Operator:	OGRID:	
BTA OIL PRODUCERS, LLC	260297	
104 S Pecos	Action Number:	
Midland, TX 79701	50586	
	Action Type:	
	[C-141] Release Corrective Action (C-141)	

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	9/21/2021