

# Closure Report

Incident ID: NCE2003549412

## Site Description

Site Name:	MESA VERDE 18 CTB
Company:	OXY
Legal Description:	U/L: P, SECTION 18, T24S, R32E
County:	LEA COUNTY, NM
GPS Coordinates:	N32.21240 W103.70865

## Release Data

Date of Release:	8/28/2019
Type of Release:	CRUDE OIL
Source of Release:	INLET 90 FROM VRT TO TANKS WAS LOOSENEED ACCIDENTLY
Volume of Release:	10 BBLS CRUDE OIL/ 0 BBLS PRODUCED WATER
Volume Recovered:	9 BBLS CRUDE OIL/ 0 BBLS PRODUCED WATER

## Remediation Specifications

Remediation Parameters	PRESSURE WASH LINER WITH VACCUM TRUCK
Remediation Activities:	8/23/2021 & 8/25/2021

Plan Sent to OCD:	4/1/2020	FROM CLIFF TO RYAN MANN WITH STATE.NM.US
OCD Approval of Plan:		
Plan Sent to BLM:	2/19/2020	FROM CLIFF TO SPILL@BLM.GOV AND WADE
BLM Approval of Plan:		

## Supporting Documentation

Google Earth Map of leak area	
Closure pictures 8/25/2021	
Signed pg. 6 C-141	
Closure Liner Report	

## Request for Closure

Based on the completion of the remediation plan as agreed upon, BBC International requests closure approval from NMOCD.

Cliff Brunson, President of BBC International Inc.

8/26/2021

# Liner Inspection Report

Operator: OXY

Site Name: MESA VERDE 18 CTB

Leak Date: 8/28/2019

Inspection Date: 8/25/2021

## Inspection Results:

Liner Integrity:    Good ☒    Bad ☐

Debris Removal:    Yes ☐    No ☒

## Remediation Activities:

Gravel Removal:    Yes ☐    No ☒

Power Wash:    Yes ☒    No ☐

Closure Photos: ☒

Inspected By: KELLY

Date: 8/25/2021

Form C-141

Page 6

State of New Mexico  
Oil Conservation Division

Incident ID	NCE2003549412
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.


**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Wade Dittrich Title: Environmental CoordinatorSignature:  Date: 9-9-21email: wade\_dittrich@oxy.com Telephone: (575) 390-2828**OCD Only**Received by: Chad Hensley Date: 10/12/2021

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 10/12/2021Printed Name: Chad Hensley Title: Environmental Specialist Advanced

MESA VERDE 18 CTB

8/28/19





MESA VERDE 18 CTB

8/28/19



MESA VERDE 18 CTB

8/28/19



**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 49494

**CONDITIONS**

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 49494
	Action Type: [C-141] Release Corrective Action (C-141)

**CONDITIONS**

Created By	Condition	Condition Date
chensley	None	10/12/2021