## Diablo Analytical BTU Report GPA 2145-16 Analysis

## Sample Information

	Sample Information
Sample Name	M11-108H R2
Station Number	
Taken By	Gas Analysis Service
Operator	DJR
Method Name/Type	GAS High w H2S.met
Injection Date	2021-10-25 11:15:39
Report Date	2021-10-25 11:21:13
EZReporter Configuration File	Standard Sample GAS edit SC 7-12-21.cfgx
Source Data File	2021-10-25 11-15-28 (GMT -06-00)M11-108H R-Rep2.dat
EZReporter Data File	20211025-112113-M11-108H R2.ezrx
Data Source	Agilent EZChrom Connector

## **Component Results**

Component Name	Raw Amount	Norm%	Gross HV (Dry) (BTU / Ideal cu.ft.)	GPM (Dry) (Gal. / 1000 cu.ft.)
Nitrogen	35.4977	38.2803	0.0	4.220
Methane	42.3459	45.6654	462.3	7.757
Carbon Dioxide	0.2582	0.2784	0.0	0.048
Ethane	6.3727	6.8722	121.9	1.842
Hydrogen Sulfide	0.0000	0.0000	0.0	0.000
Propane	5.0895	5.4884	138.4	1.515
i-Butane	0.5593	0.6031	19.7	0.198
n-Butane	1.4574	1.5716	51.4	0.496
i-Pentane	0.3636	0.3921	15.7	0.144
n-Pentane	0.3700	0.3990	16.0	0.145
Hexanes Plus	0.4168	0.4495	23.1	0.195
Total:	92.7311	100.0000	848.5	16.560

## **Results Summary**

Result	Dry	Sat. (Base)
Total Raw Mole% (Dry)	92.7311	
Total Normalzed Mole%	100.0000	0.0000
Pressure Base (psia)	14.730	
Temperature Base	60.0	
Flowing Temperature (Deg. F)	0.0	
Flowing Pressure (psia)	0.0	
Water Mole%	-	0.0000
Gross Heating Value (BTU / Ideal cu.ft.)	848.5	0.0
Gross Heating Value (BTU / Real cu.ft.)	850.5	0.0
Net Heating Value (BTU / Ideal cu.ft.)	771.4	0.0
Relative Density (G), Real	0.8617	0.0000
Compressibility (Z) Factor	0.9977	0.0000
Total GPM	16.560	0.000

•

<b>J</b> DJR	Energ	Ŋ	Flare Repo	rt	
Report created:	Tuesday, October 26	5. 2021 7:15:50 AM			
Created by:		, ,,,,,,,, _			
Time	Facility Desc	Flow Rate	N2	Gas Flared	Gas Sold
BTWU M11 108H					
10/8/2021 12:00:00 AM	BTWU M11 108H				,
10/9/2021 12:00:00 AM	BTWU M11 108H				
10/10/2021 12:00:00 AM	BTWU M11 108H	269.22			,
10/11/2021 12:00:00 AM	BTWU M11 108H	142.1			
10/12/2021 12:00:00 AM	BTWU M11 108H	25.25		1	,
10/13/2021 12:00:00 AM	BTWU M11 108H	6.12			
10/14/2021 12:00:00 AM	BTWU M11 108H	3.51			
10/15/2021 12:00:00 AM	BTWU M11 108H	3.18	48.5	5	
10/16/2021 12:00:00 AM	BTWU M11 108H	1.43	45.4	0.64922	0.78078
10/17/2021 12:00:00 AM	BTWU M11 108H	704.32	45.4	319.76128	384.55872
10/18/2021 12:00:00 AM	BTWU M11 108H	1129.97	43.7	493.79689	636.17311
10/19/2021 12:00:00 AM	BTWU M11 108H	1113.96	43.7	486.80052	627.15948
10/20/2021 12:00:00 AM	BTWU M11 108H	1073.14	38.9	417.45146	655.68854
10/21/2021 12:00:00 AM	BTWU M11 108H	1100.04	38.9	427.91556	672.12444
10/22/2021 12:00:00 AM	BTWU M11 108H	1173.91	38.9	456.65099	717.25901
10/23/2021 12:00:00 AM	BTWU M11 108H	1208.58	38.9	470.13762	738.44238
10/24/2021 12:00:00 AM	BTWU M11 108H	1181.33	38.9	459.53737	721.79263
10/25/2021 12:00:00 AM	BTWU M11 108H	1139.49	35.4	403.37946	736.11054
10/26/2021 12:00:00 AM	BTWU M11 108H	1126.37	35.4	398.73498	727.63502



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Page 5 of 6

Action 57959

QUESTIONS

Operator:	OGRID:			
DJR OPERATING, LLC 1 Road 3263	371838 Action Number:			
Aztec, NM 87410	57959			
	Action Type: [C-129] Venting and/or Flaring (C-129)			
QUESTIONS				
Prerequisites				
Any messages presented in this section, will prevent submission of this application. Please resolve	hese issues before continuing with the rest of the questions.			
Incident Well	[30-045-35515] BETONNIE TSOSIE WASH UNIT #108H			
Incident Facility	Not answered.			
Determination of Reporting Requirements				
Answer all questions that apply. The Reason(s) statements are calculated based on your answers an	nd may provide addional guidance.			
Was or is this venting and/or flaring caused by an emergency or malfunction	Yes			
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes			
Is this considered a submission for a venting and/or flaring event	Yes, major venting and/or flaring of natural gas.			
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v	enting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.			
Was there or will there be <b>at least 50 MCF</b> of natural gas vented and/or flared				
during this event	Yes			
Did this venting and/or flaring result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public	No			
health, the environment or fresh water				
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	Νο			
England and have been				
Equipment Involved				
Primary Equipment Involved Producing Well				
Additional details for Equipment Involved. Please specify	Not answered.			
Representative Compositional Analysis of Vented or Flared Natural Gas				
Please provide the mole percent for the percentage questions in this group.				
Methane (CH4) percentage	46			
Nitrogen (N2) percentage, if greater than one percent	38			
Hydrogen Sulfide (H2S) PPM, rounded up	0			
Carbon Dioxide (C02) percentage, if greater than one percent	0			
Oxygen (02) percentage, if greater than one percent	0			
If you are venting and/or flaring because of Pipeline Specification, please provide the required spec	ifications for each gas.			
Methane (CH4) percentage quality requirement	Not answered.			
Nitrogen (N2) percentage quality requirement	Not answered.			
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.			
Carbon Dioxide (C02) percentage quality requirement	Not answered.			
Oxygen (02) percentage quality requirement	Not answered.			
Date(s) and Time(s)				
	10//7/0001			
Date venting and/or flaring was discovered or commenced	10/17/2021			
Time venting and/or flaring was discovered or commenced	12:00 AM			
Time venting and/or flaring was terminated	12:00 AM			
Cumulative hours during this event	240			
Measured or Estimated Volume of Vented or Flared Natural Gas				

#### Natural Gas Vented (Mcf) Details

Not answered.

## Received by OCD: 10/26/2021 1:07:17 PM

٦

Natural Gas Flared (Mcf) Details	Cause: Other   Producing Well   Natural Gas Flared   Released: 4,334 Mcf   Recovered: 0 Mcf   Lost: 4,334 Mcf ]	
Other Released Details	Not answered.	
Additional details for Measured or Estimated Volume(s). Please specify	High N2 from offset wellbore communication.	
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.	

Venting or Flaring Resulting from Downstream Activity			
Was or is this venting and/or flaring a result of downstream activity	Yes		
Was notification of downstream activity received by you or your operator	Yes		
Downstream OGRID that should have notified you or your operator	[371838] DJR OPERATING, LLC		
Date notified of downstream activity requiring this venting and/or flaring	09/28/2021		
Time notified of downstream activity requiring this venting and/or flaring	12:00 AM		

_				
Steps	and Ac	tions to	Prevent	Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True			
Please explain reason for why this event was beyond your operator's control	offset wellbore communication			
Steps taken to limit the duration and magnitude of venting and/or flaring	install & monitor flare stack. Flare until N2 and/or O2 are cleaned from wellbore & natural gas can meet gathering pipeline specs. Sent to pipeline as soon as specs are met.			
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	monitor offset well communication			

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DJR OPERATING, LLC	371838
1 Road 3263	Action Number:
Aztec, NM 87410	57959
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

#### CONDITIONS

Created By	Condition	Condition Date
scrues76	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	10/26/2021

Page 7 of 6

.

Action 57959