

Meter #: 17780-00

Name: NO VAC ABO UN TR10

Totals

Sample

Date: 02/24/2021

Type: Spot

 Pressure:
 34.0
 H2O:
 lbs/mm

 Temperature:
 48.0
 H2S:
 2,352 ppm

Component	Mole %	Liquid Content	Mass %
Carbon Dioxide, CO2	0.2757		0.4956
Nitrogen, N2	3.0033		3.4362
Methane, C1	64.6994		42.3925
Ethane, C2	15.8330	4.2539	19.4445
Propane, C3	10.1801	2.8175	18.3342
Isobutane, iC4	1.1046	0.3631	2.6222
n-Butane, nC4	2.6766	0.8477	6.3539
Isopentane, iC5	0.5985	0.2199	1.7636
n-Pentane, nC5	0.5523	0.2011	1.6275
Hexanes Plus, C6+	0.8414	0.3689	3.2024
Water, H2O			
Hydrogen Sulfide, H2S	0.2352		0.3274
Oxygen, O2	0.0000		0.0000
Carbon Monoxide, CO			
Hydrogen, H2			
Helium, He	0.0000		0.0000
Argon, Ar			

100.0001

Property	Total Sample
Pressure Base	14.730
Temperature Base	60.00
Relative Density	0.8491
HV, Dry @ Base P,T	1412.34
HV, Sat @ Base P, T	1387.62
HV, Sat @ Sample P, T	
Fws Factor	
Cricondentherm	
HCDP @ Sample Pressure	
Free Water GPM	
Stock Tank Condensate Brls/mm	
26 # RVP Gasoline	1.186
Testcar Permian	0.769
Testcar Panhandle	0.904
Testcar Midcon	0.863

100.0000

9.0721

NVAU 95 BTY

MTD Avg Gas – Prod Gas = Vented Gas/ Day

08/15/2021 - 08/15/2021 = 180

Pressure Base Conversion

14.73/15.025 = .98036605

180* .98036605 = **176 MCF Vented**

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 62372

QUESTIONS

ı	Operator:	OGRID:
ı	CROSS TIMBERS ENERGY, LLC	298299
ı	400 West 7th Street	Action Number:
ı	Fort Worth, TX 76102	62372
ı		Action Type:
ı		[C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites	
Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.	
Incident Well	Not answered.
Incident Facility	[fAPP2123050486] NORTH VACUUM ABO 95 BATTERY

Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.		
Was or is this venting and/or flaring caused by an emergency or malfunction	Yes	
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes	
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or flaring of natural gas.	
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.		
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes	
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	FLARE STACK

Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	65	
Nitrogen (N2) percentage, if greater than one percent	3	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.		
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

Date(s) and Time(s)	
Date venting and/or flaring was discovered or commenced	08/15/2021
Time venting and/or flaring was discovered or commenced	12:00 AM
Time venting and/or flaring was terminated	11:59 PM
Cumulative hours during this event	24

I Natural Gas vented (Mich Details	stream Emergency Maintenance Other (Specify) Natural Gas Vented 76 Mcf Recovered: 0 Mcf Lost: 176 Mcf]

Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	FLARE STACK
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting and/or flaring a result of downstream activity	No
Was notification of downstream activity received by you or your operator	Not answered.
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	DCP MIDSTREAM EQUIPMENT FAILURE
Steps taken to limit the duration and magnitude of venting and/or flaring	DURATION AND MAGNITUDE OUT OF OUR CONTROL DUE TO MIDSTREAM EQUIPMENT FAILURE
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	CAUSE AND REOCCURANCE OUT OF OUR CONTROL DUE TO MIDSTREAM EQUIPMENT FAILURE

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 62372

CONDITIONS

Operator:	OGRID:
CROSS TIMBERS ENERGY, LLC	298299
400 West 7th Street	Action Number:
Fort Worth, TX 76102	62372
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
savarello	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	11/17/2021