

Diablo Analytical BTU Report GPA 2145-16 Analysis

Sample Information

	Sample Information
Sample Name	L31-523H R2
Station Number	
Taken By	Gas Analysis Service
Operator	DJR
Method Name/Type	GAS High w H2S.met
Injection Date	2021-11-19 13:34:12
Report Date	2021-11-19 13:38:17
EZReporter Configuration File	Standard Sample GAS edit SC 7-12-21.cfgx
Source Data File	2021-11-19 13-33-56 (GMT -07-00)L31-523H R-Rep2.dat
EZReporter Data File	20211119-133817-L31-523H R2.ezrx
Data Source	Agilent EZChrom Connector

Component Results

Component Name	Raw Amount	Norm%	Gross HV (Dry) (BTU / Ideal cu.ft.)	GPM (Dry) (Gal. / 1000 cu.ft.)
Nitrogen	37.3127	40.1235	0.0	4.422
Methane	42.7499	45.9701	465.4	7.807
Carbon Dioxide	0.1747	0.1879	0.0	0.032
Ethane	6.2030	6.6703	118.3	1.787
Hydrogen Sulfide	0.0000	0.0000	0.0	0.000
Propane	4.2330	4.5519	114.8	1.256
i-Butane	0.5027	0.5406	17.6	0.177
n-Butane	1.1653	1.2531	41.0	0.396
i-Pentane	0.2525	0.2715	10.9	0.099
n-Pentane	0.2190	0.2355	9.5	0.086
Hexanes Plus	0.1819	0.1956	10.1	0.085
Total:	92.9947	100.0000	787.5	16.147

Results Summary

Result	Dry	Sat. (Base)
Total Raw Mole% (Dry)	92.9947	
Total Normalized Mole%	100.0000	0.0000
Pressure Base (psia)	14.730	
Temperature Base	60.0	
Flowing Temperature (Deg. F)	0.0	
Flowing Pressure (psia)	0.0	
Water Mole%	-	0.0000
Gross Heating Value (BTU / Ideal cu.ft.)	787.5	0.0
Gross Heating Value (BTU / Real cu.ft.)	789.1	0.0
Net Heating Value (BTU / Ideal cu.ft.)	715.1	0.0
Relative Density (G), Real	0.8403	0.0000
Compressibility (Z) Factor	0.9980	0.0000
Total GPM	16.147	0.000

Well Name	Date	Prams Total	Hours Flared	Hours Produced	Actual Gas	Flared Volumes
NAU L31-523	11/25/2021	49.9	7	0	0	49.9



District I1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720**District II**811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720**District III**1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170**District IV**1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 65443

QUESTIONS

Operator: DJR OPERATING, LLC 1 Road 3263 Aztec, NM 87410	OGRID: 371838
	Action Number: 65443
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	[30-043-21341] N ALAMITO UNIT #523H
Incident Facility	Not answered.

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	No
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	No
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Producing Well
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	46
Nitrogen (N2) percentage, if greater than one percent	40
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	11/25/2021
Time venting and/or flaring was discovered or commenced	06:00 PM
Time venting and/or flaring was terminated	11:59 PM
Cumulative hours during this event	7

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Other Producing Well Natural Gas Flared Released: 50 Mcf Recovered: 0 Mcf Lost: 50 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting and/or flaring a result of downstream activity	No
Was notification of downstream activity received by you or your operator	No
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	Well was hit by nearby completions activity and nitrogen concentrations exceed pipeline specifications.
Steps taken to limit the duration and magnitude of venting and/or flaring	Well was hit by nearby completions activity and nitrogen concentrations exceed pipeline specifications.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Flaring will conclude once nitrogen concentrations are below pipeline specifications.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 65443

CONDITIONS

Operator: DJR OPERATING, LLC 1 Road 3263 Aztec, NM 87410	OGRID: 371838
	Action Number: 65443
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
farrell	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	12/7/2021