District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2206337228
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

					- 3		
Responsible	e Party: En	terprise Field S	ervices, LLC	OGRID: 2	241602		
Contact Name: Thomas Long			Contact T	tact Telephone: 505-599-2286			
Contact em	ail: tjlong@	eprod.com		Incident #	Incident # (assigned by OCD) nAPP2206337228		
Contact ma 87401	iling addres	ss: 614 Reilly Av	e, Farmington,	NM			
			Location o	of Release S	Source		
Latitude <u>36.</u>	438720		Longitude_	-107.611543	^	IAD 83 in decimal degrees to 5 decimal places)	
Site Name: I	Lateral 2C-	-6				Site Type Natural Gas Gathering Pipeline	
Date Releas	e Discover	ed: 03/02/2022				Serial # (if applicable) N/A	
Unit Letter	Section	Township	Range	Cour	nty		
0	31	26N	7W	Rio Ar	riba		
Surface Own			Nature and	Volume of			
Crude O		Released (Select all to Volume Releas		calculations or specif		n for the volumes provided below) Recovered (bbls)	
Produced Water Volume Released (bbls):				Recovered (bbls):			
	u vvatoi	Is the concentr	ation of dissolver >10,000 mg/l?	d chloride in the	Yoldine	□ No	
☐ Condensate Volume Released (bbls):3-5 BBLs		BLs	Volume	Recovered (bbls): None			
		F	Volume Recovered (Mcf): None				
Other (describe) Volume/Weight Released (provide units)		Volume/Weight Recovered (provide units)					
Lubrication	Oil						
isolated, depr The release f	ressurized, lo flowed down	ocked and tagged o a small hill approx	out. No residents with the imately 200 feet. A	vere affected. No w	ashes were nately 200	ate from the Lateral 2C-6. The meter tube was affected. No emergency services responded. feet long by one foot wide was affected by the	

All free liquids and recoverable materials have been removed and managed appropriately. If all the actions described above have not been undertaken, explain why: Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Printed Name: Thomas J. Long Title: Senior Environmental Scientist Thomas Long

Telephone: 505-599-2286


Date: 3/10/2022

Received by: ____Ramona Marcus

email: tilong@eprod.com_____

Signature:

OCD Only



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 87995

CONDITIONS

Operator:	OGRID:
Enterprise Field Services, LLC	241602
PO Box 4324	Action Number:
Houston, TX 77210	87995
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	The submitted C-141 is accepted with the following condition(s): The lateral and longitudinal information does not match the ULSTR regarding the release location. Please correct the conflicting information and report back to OCD. The latitude and longitude information (36.43872,-107.611543) on the C-141 resulted in the following ULSTR: P-31-26N-07W.	3/10/2022