District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Released to Imaging: 7/27/2022 9:07:52 AM

Incident ID	nAPP2220760390
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

				1.	V
Responsible Party 3Bear Field Services, LLC			, LLC	OGR	RID 372603
Contact Name Kevin Adams				Cont	act Telephone 409-553-1480
Contact ema	Contact email kevin.adams@deleklogistics.com			Incid	dent # (assigned by OCD) nAPP2220760390
Contact mail	ing address	12700 Park Centr	al Drive, Suite 70	00 Dallas, TX 2	75271
			,		
			Location	ı of Releas	se Source
Latitude	32.54251			Longit	-103.525767
	0210 120 1		(NAD 83 in de	ecimal degrees to	
Site Name	Libby Oil	Terminal		Site T	Type DOT Breakout Tanks
Date Release		7/16/2022		API#	(if applicable)
		7/10/2022			
Unit Letter	Section	Township	Range		County
G	26	20S	34E	Lea	
3 6 0			🗖		
Surface Owner	r: State	Federal Tr	ibal 🕍 Private ((Name:)
			Nature an	d Volume	of Release
	M . E	K			
Crude Oil	Materia	Volume Release	d (bbls) 0 - Fire i	h calculations or sp in pump no oil rele	pecific justification for the volumes provided below) ease Volume Recovered (bbls) 0 - no oil released
Produced	Water	Volume Release			Volume Recovered (bbls)
		Is the concentrat	· · ·	chloride in the	i i i
- <u></u>		produced water		cinoride in the	L 165 L NO
☐ Condensa	te	Volume Release	d (bbls)		Volume Recovered (bbls)
☐ Natural G	as	Volume Release	d (Mcf)		Volume Recovered (Mcf)
Other (describe) Volume/Weight Released (provide units)		le units)	Volume/Weight Recovered (provide units)		
Cause of Rele	ease				
Pump failure	e caused a fi	re. No oil released	i .		

State of New Mexico Oil Conservation Division

Incident ID	nAPP2220760390
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the respon	nsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?		was a fire. However, this is a DOT regulated and it was reported to
X Yes No		
If YES, was immediate n	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
Notice was given by I	Kevin Adams, Delek Logistics to Rosa Rom	ero, NMOCD, via phone on July 19, 2022.
	Initial Re	esponse
The responsible	party must undertake the following actions immediatel	vunless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.	
	as been secured to protect human health and	
Released materials ha	ave been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed and	d managed appropriately. N/A
	d above have <u>not</u> been undertaken, explain v	
This was a fire due to a p	ump failure. No oil was released. We are re	equesting closure of this incident since there are no
remedial actions to take.		
D 10.15.00.0 D (1) 200		
Per 19.15.29.8 B. (4) NM has begun, please attach	IAC the responsible party may commence re a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred
within a lined containmen	nt area (see 19.15.29.11(A)(5)(a) NMAC), p	lease attach all information needed for closure evaluation.
I hereby certify that the info	rmation given above is true and complete to the l	pest of my knowledge and understand that pursuant to OCD rules and
regulations all operators are public health or the environ	required to report and/or file certain release notifient. The acceptance of a C-141 report by the C	ications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have
failed to adequately investig	ate and remediate contamination that pose a threa	at to groundwater, surface water, human health or the environment. In
and/or regulations.	Ta C-141 report does not relieve the operator of i	responsibility for compliance with any other federal, state, or local laws
Printed Name: Kevin A	Adams	Title: Senior Manager, Environmental
12	M Ada	
Signature:	M. Hyams	Date:
email: kevin.adams@dele	eklogistics.com	Telephone: 409-553-1480
OCD Only		
Jocelyn I	Harimon	07/27/2022
Received by:		Date:

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 128935

CONDITIONS

Operator:	OGRID:
3BEAR FIELD SERVICES, LLC	372603
1200 17th Street, Suite 750	Action Number:
Denver, CO 80202	128935
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	7/27/2022