District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party TAP ROCK OPERATING, LLC

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2228038497
District RP	
Facility ID	
Application ID	

## **Release Notification**

## **Responsible Party**

OGRID 372043

Contact Nam	ne CHRIST	IAN COMBS			Contact T	elephone (720)360-4028	
Contact ema	il ccombs@	taprk.com			Incident #	(assigned by OCD)	
Contact mail	Contact mailing address 523 Park Point Drive #200			Golden CO, 80401			
Latitude 32.0	067413		Location  (NAD 83 in de			-104.264250	
Site Name SCHLITZ FED COM #152H			Site Type	DRILLING			
Date Release	Discovered	10/4/22			API# (if ap	plicable) <b>30-015-49942</b>	
Unit Letter	Section	Township	Range	Ī	Cou	nty	
N	02	26S	26E	EDDY			
						e justification for the volumes provided below)	
Crude Oi	l	Volume Release	ed (bbls)			Volume Recovered (bbls)	
Produced	Water	Volume Release	ed (bbls)			Volume Recovered (bbls)	
Is the concentration of dissolved chloride produced water >10,000 mg/l?			in the	☐ Yes ☐ No			
Condensa	ite	Volume Release	ed (bbls)			Volume Recovered (bbls)	
☐ Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)			
☐ Other (describe) Volume/Weight Released (provide units) 31.87BBLS			Volume/Weight Recovered (provide units) <b>0BBLS</b>				
	ransportati	on Truck was ha side of Highway		ed drill	cuttings an	d was in a wreck causing the truck to roll, releasing	

Page 2 of 4

Incident ID	NAPP2228038497
District RP	
Facility ID	
Application ID	

Was this a major	If VES for what record(s) does the many will next year it at it is a minute of
Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?  Volume
19.15.29.7(A) NMAC?	
⊠ Yes □ No	
Z 100 Z 110	
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? ber 6, 2022 to OCD Spills, Bratcher, Nobui, Hamlet
	Initial Response
The responsible j	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
M The 641	
	ease has been stopped.
	s been secured to protect human health and the environment.
	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.
<u> </u>	ecoverable materials have been removed and managed appropriately.
if all the actions described	d above have not been undertaken, explain why:
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have atte and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name: Natalie G	iladden Title: Environmental and Regulatory Director
Signature:	lu Gladden Date: 10/6/22
email: natalie@energysta	ffingllc.com Telephone: 5753906397
OCD O	
OCD Only	
Received by:Jocelyn	Harimon Date: 10/07/2022

Soil Type	Porosity	Length	Width	<b>Depth</b> (.083 per inch)	Cubic Feet	Estimated Barrels	Soil Type
Clay	0.15	207.8	69.1	0.083	1191.7953	31.87	Clay
Peat	0.40	10	10	0.083	8.3	0.59	Peat
Glacial Sediments	0.13	10	10	0.083	8.3	0.19	Glacial Sediments
Sandy Clay	0.12	10	10	0.083	8.3	0.18	Sandy Clay
Silt	0.16	10	10	0.083	8.3	0.24	Silt
Loess	0.25	10	10	0.083	8.3	0.37	Loess
Fine Sand	0.16	10	10	0.083	8.3	0.24	Fine Sand
Medium Sand	0.25	10	10	0.083	8.3	0.37	Medium Sand
Coarse Sand	0.26	10	10	0.083	8.3	0.38	Coarse Sand
Gravely Sand	0.26	10	10	0.083	8.3	0.38	Gravely Sand
Fine Gravel	0.26	10	10	0.083	8.3	0.38	Fine Gravel
Medium Gravel	0.20	10	10	0.083	8.3	0.30	Medium Gravel
Coarse Gravel	0.18	10	10	0.083	8.3	0.27	Coarse Gravel
Sandstone	0.25	10	10	0.083	8.3	0.37	Sandstone
Siltstone	0.18	10	10	0.083	8.3	0.27	Siltstone
Shale	0.05	10	10	0.083	8.3	0.07	Shale
Limestone	0.13	10	10	0.083	8.3	0.19	Limestone
Basalt	0.19	10	10	0.083	8.3	0.28	Basalt
Volcanic Tuff	0.20	10	10	0.083	8.3	0.30	Volcanic Tuff
Standing Liquids	Х	10	10	0.083	8.3	1.48	Standing Liquids

1	2	3	4	5	6
0.083	0.166	0.250	0.332	0.415	0.500
7	8	9	10	11	12
0.581	0.664	0.750	0.830	0.913	1.000

NOTE: This is an **estimate** tool designed for quick field estimates of whether a C-141 should be required (*I.e. a release is estimated to be greater than or less than 5 barrel volumes*)

Choose the one prevailing ground type for estimating spill volumes at a single location.

Note that the depth should be measured in feet and tenths of feet (1 inch = .083)

Cubic Feet = L x W x D

Estimated Barrels = ((Cubic Feet x Porosity) / 5.61)

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 149580

## **CONDITIONS**

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	149580
	Action Type:
	[C-141] Release Corrective Action (C-141)

## CONDITIONS

Created By	Condition	Condition Date
jharimon	None	10/12/2022