<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2300761990
District RP	
Facility ID	
Application ID	

Release Notification

			Resp	onsible Pai	rty	
Responsible	Party Devo	n Energy Produc	tion Company	OGRID	6137	
Contact Name Dale Woodall				Contact	Telephone 575-748-1838	
Contact ema	Contact email dale.woodall@dvn.com			Incident	# (assigned by OCD) nAPP2300761990	
		205 E. Bender		obbs, NM 882	40	
				of Release		
				Longitud	103.906784	
Site Name Al	LIED FE	7 BATTERY		Site Typ	¢BATTERY	
Date Release				API# (if a	applicable)	
Unit Letter	Section	Township	Range	Co	unty	
G	07	18S	31E	E	DDY	
Surface Owne		■ Federal □ Tr	Nature and	l Volume of		
Crude Oi		Volume Release		calculations or speci	fic justification for the volumes provided below) Volume Recovered (bbls)	
Produced	Water	Volume Release	d (bbls) 41.4		Volume Recovered (bbls) 30	
Is the concentration of total dissolved in the produced water >10,000 mg/l?			Yes No			
Condensate Volume Released (bbls)			Volume Recovered (bbls)			
☐ Natural Gas Volume Released (Mcf)			Volume Recovered (Mcf)			
Other (describe) Volume/Weight Released (provide uni		e units)	Volume/Weight Recovered (provide units)			
Cause of Rel	lurthe	rinvestigation	ne iouna ine	production (ound oil in un-lined gravel containment. After DT 2 developed a hole in the tank. LO ck due to having no way to isolate. Truck	

emptying out OT 2 and transferred remaining oil into OT 1.

- 73			-		~
v	an	a	٠,		•
- 1	uz		Air .	v	-
	- 0	_			

Incident ID	nAPP2300761990
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsion of the responsion o	nsible party consider this a major release?		
19.15.29.7(A) NMAC?	More than 20 bbis			
Yes No				
If YES, was immediate n	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?		
Yes, email to Mike	Bratcher and the OCD, by Dale \	Voodall on 1/7/2023 and via the NOR portal too.		
	Initial R	esponse		
The responsible	party must undertake the following actions immediatel	y unless they could create a safety hazard that would result in injury		
■ The source of the rele	ease has been stopped.			
<u></u>	s been secured to protect human health and	the environment.		
Released materials ha	ave been contained via the use of berms or o	likes, absorbent pads, or other containment devices.		
	ecoverable materials have been removed an			
If all the actions describe	d above have <u>not</u> been undertaken, explain	why:		
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Printed Name: Dale \	Woodall	Title: Environmental Professional		
Signature: Dale U	Poodall	Date: 1/12/2023		
email: dale.wooda		Telephone: 575-748-1838		
OCD Only				
Received by:Jocel	yn Harimon	Date:01/12/2023		

ALLIED FED 7 BATTERY

OCD incident number nAPP2300761990

1/7/2023

30 BBL Recovered

100		Bbls) Calculator Outputs in red	
Col	ntaminated S	Soil measurement	
Area (squ	are feet)	Depth(inches)	
123	38	0.500	
Cubic Feet of Soil Impacted		<u>51.583</u>	
Barrels of So	il Impacted	<u>9.19</u>	
Soil Type		Pea Gravel	
Barrels of Oil Assuming 100% Saturation		<u>4.60</u>	
Saturation	Fluid pre	sent with shovel/backhoe	
Estimated Barrels of Oil Released		4.60	
	Free Standi	ng Fluid Only	
Area (square feet)		Depth(inches)	
<u>1238</u>		2.000	
Standing fluid		<u>36.780</u>	
Total fluids spilled		41.377	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 175349

CONDITIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	175349
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jharimon	None	1/12/2023