

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
SEP 20 2007 Submit 2 Copies to appropriate
District Office in accordance
OCD-ARTESIA with Rule 116 on back
side of form

30-015-26150

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company	HARVEY E. YATES COMPANY	Contact	Clay Stevens or Jen Serrano
Address	PO Box 1933, Roswell 88202-1933	Telephone No.	(505) 623-6601
Facility Name	SOUTH TAYLOR 13 FEDERAL #4	Facility Type	Tank Battery
Surface Owner	USA	Mineral Owner	BLM
		Lease No.	NMN2537

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	13	18S	31E	1650'	SOUTH	660'	EAST	EDDY COUNTY, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Minor	Volume of Release	appx 28 bbls	Volume Recovered	bbls
Source of Release	oil tank	Date/Hour of Release	6/3/07	Date/Hour Discovered	6/4/07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Paul Evans, BLM		
By Whom?	Jen Serrano	Date and Hour	6/4/07 8:25 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		
If a Watercourse was Impacted, Describe Fully.* n/a					
Describe Cause of Problem and Remedial Action Taken.* Lost pressure on heater treater, water was sent to oil tank causing the oil to run over and onto location.					
Describe Area Affected and Cleanup Action Taken.* 90% of spill onto location, a small puddle about 10 yds off location. Vacuumed up as much possible. Used 10 gallons microblaze to 550 gal. water. Soil samples taken and analysis submitted to the OCD-Artesia office.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Jen Serrano		Approved by District Supervisor: 			
Title: Engineering Tech		Approval Date: SEP 20 2007 Expiration Date:			
E-mail Address: jserrano@heycoenergy.com		Conditions of Approval:			
Date: 09/19/07 Phone: (505)623-6601		Attached <input type="checkbox"/>			

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 185657

CONDITIONS

Operator: MATADOR PRODUCTION COMPANY One Lincoln Centre Dallas, TX 75240	OGRID: 228937
	Action Number: 185657
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	2/13/2023