

# Closure Report

INCIDENT ID # nMLB1004338184

## Site Description

Site Name:	ENCORE 12 INDIAN COM #1
Company:	Oxy USA, Inc.
Legal Description:	U/L H, Sect. 12, T21S, R23E
County:	Eddy
GPS Coordinates:	32.4958229, -104.5506287

## Release Data

Date of Release:	1/9/2010
Type of Release:	Produced water
Source of Release:	
Volume of Release:	30
Volume Recovered:	15

## Remediation Specifications

Remediation Parameters:	This site is listed on the Agreed Compliance Order of 4/5/19. This site had previously been remediated but no paperwork existed for verification. However, the OCD website indicates the site closed on 2/12/10 under the Incident number. The release occurred in a lined containment. This leak is closed.	
Remediation Activities:		
Plan Sent to OCD:		
OCD Approval of Plan:	2/12/2010	
Plan Sent to BLM:		
BLM Approval of Plan:		

## Supporting Documentation

C-141, page 6	signed and included	
Site Diagram	Google Earth map	
Pictures	Closure photos	
Lab Summary/Analysis		
Notifications		

## Request for Closure

Based on the completion of the remediation plan, OXY requests closure approval from NMOCD.

Cliff P. Brunson  
President, BBC International, Inc.

11/2/2022

Form C-141

Page 6

State of New Mexico  
Oil Conservation Division

Incident ID	nMLB1004338184
District RP	
Facility ID	
Application ID	


## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Wade Dittrich Title: Environmental Coordinator  
Signature:  Date: 8.30.22  
email: wade\_dittrich@oxy.com Telephone: (575) 390-2828

**OCD Only**

Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 3/21/2023  
Printed Name: Brittany Hall Title: Environmental Specialist

Closure approved 2/12/2010. Uploading to document incident file for information. Pictures show integrity of liner.

SIGN-IN    HELP

Searches

Operator Data

Hearing Fee Application

## OCD Permitting

Home    Searches    Incidents    Incident Details

### NMLB1004338184 2010 MAJOR I SWS @ 30-015-35632

#### General Incident Information

Site Name:

Well: [30-015-35632] ENCORE 12 INDIAN COM #001

Facility:

Operator: [192463] OXY USA WTP LIMITED PARTNERSHIP

Status: Closure Approved

Type: Produced Water Release

District: Artesia

Severity:

Major

Surface Owner:

Federal

County:

Eddy (15)

Incident Location: H-12-21S-23E 1650 FNL 990 FEL

Lat/Long: 32.4958229,-104.5506287 NAD83

Directions:

Quick

- [Gene](#)
- [Mater](#)
- [Eveni](#)
- [Order](#)

Assoc

- [Incide](#)
- [Well I](#)

New

- [New |](#)
- [New |](#)
- [New |](#)
- [New |](#)
- [New |](#)
- [New |](#)
- [New |](#)

#### Notes

Source of Referral: Industry Rep

Action / Escalation:

Resulted In Fire:

Will or Has Reached Watercourse:

Endangered Public Health:

Property Or Environmental Damage:

Fresh Water Contamination:

#### Contact Details

Contact Name:

Contact Title:

#### Event Dates

Date of Discovery: 01/10/2010

OCD Notified of Release:

Extension Date:

Cancelled Date:

Initial C-141 Received:

Characterization Report Approved:

Characterization Report Received:

Remediation Plan Approved:

Remediation Plan Received:

Remediation Due:

Closure Report Received:

Closure Report Approved: 02/12/2010

#### Compositional Analysis of Vented and/or Flared Natural Gas

No Compositional Analysis Found

#### Incidents Materials

Cause	Source	Material	Volume				Units
			Unk.	Released	Recovered	Lost	
Equipment Failure	Valve	Produced Water	3	30	15	15	BBL

[SIGN-IN](#) [HELP](#)

[Searches](#)

[Operator Data](#)

[Hearing Fee Application](#)

removed and replaced.

### Orders

No Orders Found

New Mexico Energy, Minerals and Natural Resources Department | Copyright 2012  
1220 South St. Francis Drive | Santa Fe, NM 87505 | P: (505) 476-3200 | F: (505) 476-3220

[EMNRD Home](#) [OCD Main Page](#) [OCD Rules](#) [Help](#)

# OXY-ENCORE 12 INDIAN COM #1

LEAK DATE: 1/9/10

EDDY CO, NM

INCIDENT #: nMLB1004338184

Google Earth


Released to Imaging: 3/21/2023 1:50:33 PM



100 ft



OXY – ENCORE 12 INDIAN COM #1 (1-9-10)





OXY – ENCORE 12 INDIAN COM #1 (1-9-10)





OXY – ENCORE 12 INDIAN COM #1 (1-9-10)





OXY – ENCORE 12 INDIAN COM #1 (1-9-10)





OXY – ENCORE 12 INDIAN COM #1 (1-9-10)



**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS  
  
Action 155651

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 155651
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
bhall	None	3/21/2023