

Closure Report

Site Description

Site Name:	Sundance Federal A CTB
Company:	Oxy USA Inc.
Legal Description:	U/L H, Section 5, T24S, R31E
County:	Eddy County, NM
GPS Coordinates:	N 32.24782 W-103.79074

Release Data

Date of Release:	2/14/18
Type of Release:	Oil and Produced water
Source of Release:	ESD valve failure cause tank spill
Volume of Release:	5 bbls oil, 7 bbls produced water
Volume Recovered:	3 bbls

Remediation Specifications

Remediation Parameters:	Excavate the areas of SP1, SP2, SP3, SP4, SP6, and SP8 to a depth of 1 foot. Excavate the areas of SP5 and SP7 to a depth of 4 feet. Backfill the site with clean soil.	
Remediation Activities:	1/2/19 to 3/7/19	
Plan Sent to OCD:	6/17/18	Email from Cliff Brunson to Mike Bratcher
OCD Approval of Plan:	6/21/18	Email from Mike Bratcher to Cliff Brunson
Plan Sent to BLM:	6/17/18	Email from Cliff Brunson to Shelly Tucker
BLM Approval of Plan:	7/11/18	Email from Shelly Tucker to Cliff Brunson

Supporting Documentation

Initial C-141	Signed 2/15/18
C-141, page 6	Signed 3/11/19
Site Diagram	June 2018
Pictures	Remediation pictures prior to and after backfill

Request for Closure

Based on the completion of the remediation plan, BBC International, Inc. requests closure approval from NMOCD.

Cliff Brunson, President, BBC International, Inc.


03/11/2019

Oxy, Sundance Federal A CTB

Leak date: 02/14/2018
Eddy County, NM
API# 30-015-33384
2RP-4622

Legend

- 1 ft Excavation
- 4 ft Excavation
- Cardinal sample points
- Leak area (blue outline)
- Sample points























Incident ID	
District RP	2RP-4622
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Wade Dittrich Title: Environmental Coordinator

Signature: _____ Date: _____

email: wade_dittrich@oxy.com Telephone: (575) 390-2828

OCD Only

Received by: _____ Date: _____

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Brittany Hall Date: 4/5/2023

Printed Name: Brittany Hall Title: Environmental Specialist

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 203445

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 203445
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
bhall	None	4/5/2023