

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: <b>COG Operating LLC (OGRID #229137)</b>	Contact: <b>Robert McNeill</b>
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No. <b>432-683-7443</b>
Facility Name: <b>MONCRIEF STATE #003</b>	Facility Type: <b>Battery</b>

Surface Owner: <b>Private</b>	Mineral Owner: <b>State</b>	API No. <b>30-015-039493</b>
-------------------------------	-----------------------------	------------------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	23	17S	28E	2230	South	730	West	Eddy

Latitude: 32.8193588 Longitude: - 104.1529236 NAD83

### NATURE OF RELEASE

Type of Release: <b>Produced Water &amp; Oil</b>	Volume of Release: <b>70 bbls pw; 7 bbls Oil</b>	Volume Recovered: <b>69 bbls pw; 6 bbls Oil</b>
Source of Release: <b>Fittings/Connections</b>	Date and Hour of Occurrence: <b>09-16-2017 09:00am</b>	Date and Hour of Discovery: <b>09-16-2017 09:00am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Crystal Weaver NMOCD; Amber Groves NMSLO</b>	
By Whom? <b>Dakota Neel</b>	Date and Hour: <b>09-16-2017 10:41PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The release occurred when the nipple broke off from the strainer on the water tank going to water pump. The nipple was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release remained within the lined facility. Vacuum trucks were dispatched to recover all free fluids. A final inspection has been conducted regarding the clean-up efforts. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Aaron Lieb</b>		Approved by Environmental Specialist: 	
Title: <b>Senior HSE Coordinator</b>		Approval Date: <b>5/2/2023</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>alieb@concho.com</b>		Conditions of Approval:	
Date: <b>November 8<sup>th</sup>, 2017</b> Phone: <b>575-748-1553</b>		Attached <input type="checkbox"/>	
		none	

\* Attach Additional Sheets If Necessary

## Hall, Brittany, EMNRD

---

**From:** Aaron Lieb  
**Sent:** Wednesday, November 8, 2017 3:50 PM  
**To:** Weaver, Crystal, EMNRD (Crystal.Weaver@state.nm.us); Amber Groves (agroves@slo.state.nm.us); Mike Bratcher (Mike.Bratcher@state.nm.us) (Mike.Bratcher@state.nm.us)  
**Cc:** Rebecca Haskell; Dakota Neel; Sheldon Hitchcock; Christopher Gray  
**Subject:** (C-141 Final) Moncrief State #003 09-16-2017 (30-015-039493)  
**Attachments:** (C-141 Final) Moncrief State #003 09-16-2017 (30-015-039493).pdf

Ms. Weaver/Ms. Groves,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

**Aaron Lieb**

Senior HSE Coordinator

COG Operating LLC

Cell: 432.557.5355

Office: 575.748.1553

[alieb@concho.com](mailto:alieb@concho.com)

2407 Pecos Avenue

Artesia, NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you

received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 206625

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 206625
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
bhall	None	5/2/2023