

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Biscuit Hills SWD #001	Facility Type: SWD
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-28142	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	29	17S	31E	950	South	1,980	East	Eddy

Latitude 32.8009262 Longitude -103.8896942

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 10 bbl. Oil & 1,170 bbl. PW	Volume Recovered: 5 bbl. Oil & 1,160 bbl. PW
Source of Release: Eight-Inch Line	Date and Hour of Occurrence: August 29, 2017 7:00 am	Date and Hour of Discovery: August 29, 2017 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Weaver – NMOCD / Ms. Tucker – BLM	
By Whom? Rebecca Haskell	Date and Hour: August 29, 2017 3:19 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was caused when an eight-inch line going from the charge pump to the H-Pump separated.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 5/5/2023	Expiration Date: n/a	
E-mail Address: dneel2@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: December 11, 2017 Phone: 575-746-2010	none		

* Attach Additional Sheets If Necessary

Abbott, Sam

From: Dakota Neel
Sent: Monday, December 11, 2017 12:08 PM
To: Weaver, Crystal, EMNRD; stucker@blm.gov
Cc: Mike Bratcher (Mike.Bratcher@state.nm.us); Jim Amos (jamos@blm.gov); Rebecca Haskell; Robert McNeill; Sheldon Hitchcock; Christopher Gray
Subject: (C-141 Final) Biscuit Hills SWD #001 8/29/17 (30-015-28142) 2RP-4371
Attachments: Biscuit Hills SWD #001 Final C-141 8-29-17 (30-015-28142).pdf

Ms. Weaver/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



From: Rebecca Haskell

Sent: Wednesday, August 30, 2017 9:07 AM

To: Weaver, Crystal, EMNRD; stucker@blm.gov

Cc: Mike Bratcher (Mike.Bratcher@state.nm.us); Jim Amos (jamos@blm.gov)

Subject: (C-141 Initial) Biscuit Hills SWD #001 8/29/17 (30-015-28142)

Ms. Weaver / Ms. Tucker,

Please find the attached Initial C-141 for your consideration. If you have any questions or concerns please contact me.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 206628

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 206628
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
bhall	None	5/5/2023