

Certificate of Analysis

Number: 6030-22100366-001A

Artesia Laboratory 200 E Main St. Artesia, NM 88210 Phone 575-746-3481

Alex Batista

Taprock

602 Park Point Drive

Ste. 200

Golden, CO 80401

Station Name: Poseidon SC CTB Sales A

Station Number: 7060363 Sample Point: Meter Run

Formation: Monthly County: Lea, NM Type of Sample: Spot-Cylinder

Heat Trace Used: N/A

Sampling Method: Fill and Purge

Sampling Company: SPL

Sampled By: Jason Bealer Sample Of: Gas Spot

Sample Date: 10/21/2022 10:13

Sample Conditions: 108.7 psig, @ 78.5 °F Ambient: 65 °F

Oct. 25, 2022

10/21/2022 10:13 Effective Date: Method: GPA-2261M Cylinder No: 1111-006913

Instrument: 70104251 (Inficon GC-MicroFusion)

Last Inst. Cal.: 10/17/2022 0:00 AM

Analyzed: 10/25/2022 09:18:15 by EBH

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia		
Hydrogen Sulfide	0.000	0.001	0.002		GPM TOTAL C2+	4.664
Nitrogen	2.142	2.167	2.718		GPM TOTAL C3+	2.246
Methane	73.703	74.572	53.562		GPM TOTAL iC5+	0.552
Carbon Dioxide	6.937	7.019	13.830			
Ethane	8.906	9.011	12.131	2.418		
Propane	4.032	4.079	8.053	1.127		
Iso-butane	0.530	0.536	1.395	0.176		
n-Butane	1.223	1.237	3.219	0.391		
Iso-pentane	0.338	0.342	1.105	0.125		
n-Pentane	0.354	0.358	1.156	0.130		
Hexanes Plus	0.670	0.678	2.829	0.297		
	98.835	100.000	100.000	4.664		
Calculated Physical P	roperties	To	otal	C6+		
Relative Density Real G	-	0.77	736	3.2176		
Calculated Molecular Weight		22	.34	93.19		
Compressibility Factor	· ·	0.99	965			
GPA 2172 Calculation	:					
Calculated Gross BTU	J per ft ³ @ 14.73 ps	sia & 60°F				
Real Gas Dry BTU			143	5141		
Water Sat. Gas Base BTU		11	123	5052		
Ideal, Gross HV - Dry a	t 14.73 psia	113	8.5	5141.1		
Ideal, Gross HV - Wet		111		5051.6		
Net BTU Wet Gas - rea		4.0)18			

Comments: H2S Field Content 5 ppm

Hydrocarbon Laboratory Manager

The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality

assurance, unless otherwise stated.

Quality Assurance:

FLARING SUMMARY

Battery	Date	Total Flare Vol (mcf)	Hrs Flared	Start		End	

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 246706

DEFINITIONS

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	246706
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- · venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 246706

Phone: (505) 476-3470 Fax: (505) 476-3462		
Q	QUESTIONS	
Operator:		OGRID:
TAP ROCK OPERATING, LLC		372043
523 Park Point Drive Golden, CO 80401		Action Number: 246706
		Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve	these issues before continuing w	vith the rest of the questions.
Incident Well	Unavailable.	
Incident Facility	[fAPP2126032846] Posei	don CTB
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers a	and may provide addional guidanc	re.
Was this vent or flare caused by an emergency or malfunction	No	
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No	
Is this considered a submission for a vent or flare event	Yes, minor venting and/o	r flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during		
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes	,
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	75	
Nitrogen (N2) percentage, if greater than one percent	2	
Hydrogen Sulfide (H2S) PPM, rounded up	5	
Carbon Dioxide (C02) percentage, if greater than one percent	7	
Oxygen (02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent	U	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specific	cifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

<u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 246706

Phone:(505) 476-3470 Fax:(505) 476-3462	
QUESTI	ONS (continued)
Operator:	OGRID:
TAP ROCK OPERATING, LLC 523 Park Point Drive	372043 Action Number:
Golden, CO 80401	246706
	Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS	•
Date(s) and Time(s)	
Date vent or flare was discovered or commenced	07/21/2023
Time vent or flare was discovered or commenced	12:01 AM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	2
Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
	Cause: Normal Operations Tank (Any) Natural Gas Flared Released: 202 Mcf
Other Released Details	Recovered: 0 Mcf Lost: 202 Mcf.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.
Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.
F	
Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
,	
Please explain reason for why this event was beyond this operator's control	The location experienced normal operations and the flaring can be attributed to flash
	gas/tank vapors coming off the tank and going to low pressure flare.
Steps taken to limit the duration and magnitude of vent or flare	Standard PM. Worked with vendor to coordinate service time and minimize downtime.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Standard PM. No way to avoid periodic downtime for maintenance/repairs to address
1	unforeseen issues.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 246706

ACKNOWLEDGMENTS

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	246706
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

I acknowledge that I am authorized to submit a Venting and/or Flaring (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 246706

CONDITIONS

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	246706
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
mlaruecdh	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/1/2023