



Natural Gas Analysis Report

GPA 2172-09/API 14.5 Report with GPA 2145-16 Physical Properties

| | Sample Information |
|----------------------------------|--------------------------------------|
| Sample Name | RED TANK 27 28 CTB CHECK |
| Technician | ANTHONY DOMINGUEZ |
| Analyzer Make & Model | INFICON MICRO GC |
| Last Calibration/Validation Date | 03-16-2023 |
| Meter Number | 16200C |
| Air temperature | 66 |
| Flow Rate (MCF/Day) | |
| Heat Tracing | HEATED HOSE & GASIFIER |
| Sample description/mtr name | RED TANK 27 28 CTB CHECK |
| Sampling Method | FILL & EMPTY |
| Operator | OCCIDENTAL PETROLEUM |
| State | NEW MEXICO |
| Region Name | PERMIAN_RESOURCES |
| Asset | NEW MEXICO |
| System | EAST |
| FLOC | OP-L2152-BT002 |
| Sample Sub Type | PRODUCTION |
| Sample Name Type | WELL |
| Vendor | AKM MEASUREMENT |
| Cylinder # | 7407 |
| Sampled by | JONATHAN ALDRICH |
| Sample date | 3-15-2023 |
| Analyzed date | 3-16-2023 |
| Method Name | C9 |
| Injection Date | 2023-03-16 09:27:07 |
| Report Date | 2023-03-16 09:32:14 |
| EZReporter Configuration File | 1-16-2023 OXY GPA C9+ H2S #2.cfgx |
| Source Data File | 79256edd-11d1-456e-a9c1-97fd3ac7df68 |
| NGA Phys. Property Data Source | GPA Standard 2145-16 (FPS) |
| Data Source | INFICON Fusion Connector |

Component Results

| Component Name | Peak Area | Raw Amount | Response Factor | Norm Mole% | Gross HV (Dry) (BTU / Ideal cu.ft.) | Relative Gas Density (Dry) | GPM (Dry) (Gal. / 1000 cu.ft.) | |
|----------------|-----------|------------|-----------------|------------|-------------------------------------|----------------------------|--------------------------------|--|
| Nitrogen | 35532.0 | 2.0156 | 0.00005673 | 2.0029 | 0.0 | 0.01937 | 0.221 | |
| Methane | 966210.5 | 70.8521 | 0.00007333 | 70.4042 | 712.7 | 0.38997 | 11.984 | |
| CO2 | 49879.7 | 2.2948 | 0.00004601 | 2.2803 | 0.0 | 0.03465 | 0.391 | |
| Ethane | 283286.3 | 12.9892 | 0.00004585 | 12.9071 | 228.9 | 0.13400 | 3.466 | |
| H2S | 0.0 | 0.0003 | 0.00000000 | 0.0003 | 0.0 | 0.00000 | 0.000 | |
| Propane | 228205.6 | 7.4381 | 0.00003259 | 7.3910 | 186.4 | 0.11253 | 2.044 | |
| iso-butane | 84437.5 | 0.9377 | 0.00001111 | 0.9318 | 30.4 | 0.01870 | 0.306 | |
| n-Butane | 218974.4 | 2.4123 | 0.00001102 | 2.3970 | 78.4 | 0.04810 | 0.759 | |
| iso-pentane | 50277.3 | 0.4887 | 0.00000972 | 0.4856 | 19.5 | 0.01210 | 0.178 | |
| n-Pentane | 56698.4 | 0.5395 | 0.00000952 | 0.5361 | 21.5 | 0.01335 | 0.195 | |
| hexanes | 38745.0 | 0.2982 | 0.00000770 | 0.2963 | 14.1 | 0.00882 | 0.122 | |
| heptanes | 36786.0 | 0.2359 | 0.00000641 | 0.2344 | 12.9 | 0.00811 | 0.109 | |
| octanes | 18648.0 | 0.1094 | 0.00000587 | 0.1087 | 6.8 | 0.00429 | 0.056 | |
| nonanes+ | 3967.0 | 0.0245 | 0.00000617 | 0.0243 | 1.7 | 0.00108 | 0.014 | |
| Total: | | 100.6365 | | 100.0000 | 1313.4 | 0.80507 | 19.845 | |

Results Summary

| Result | Dry | Sat. | |
|------------------------------|----------|------|--|
| Total Un-Normalized Mole% | 100.6365 | | |
| Pressure Base (psia) | 14.730 | | |
| Temperature Base (Deg. F) | 60.00 | | |
| Flowing Temperature (Deg. F) | 83.6 | | |
| Flowing Temperature (°C) | 121.0 | | |

| Result | Dry | Sat. | |
|--|--------|--------|--|
| Gross Heating Value (BTU / Ideal cu.ft.) | 1313.4 | 1290.5 | |
| Gross Heating Value (BTU / Real cu.ft.) | 1319.1 | 1296.7 | |
| Relative Density (G), Real | 0.8082 | 0.8053 | |

Monitored Parameter Report

| Parameter | Value | Lower Limit | Upper Limit | Status | |
|----------------------------|----------|-------------|-------------|--------|--|
| Total un-normalized amount | 100.6365 | 97.0000 | 103.0000 | Pass | |

VCU FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Red Tank 27-28 OGS**Date:** 08/07/2023**Duration of event:** >8 hours/day**MCF Flared:** 64**Start Time:** 12:00 AM**End Time:** 11:59 PM**Cause:** Routine Combustion of storage tank vapors using an enclosed combustion device (VCU)**Method of Flared Gas Measurement:** VCU Meter 151312 tracking combusted gas

Comments: No wells were involved with this flaring event as this event is due to combustion of storage tank vapors by an enclosed combustion device which is used routinely at this facility, pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

1. Reason why this event was beyond Operator's control:

On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

2. Steps Taken to limit duration and magnitude of venting or flaring:

On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 253667

DEFINITIONS

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 253667 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

DEFINITIONS

| |
|--|
| For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: <ul style="list-style-type: none">• this application's operator, hereinafter "this operator";• venting and/or flaring, hereinafter "vent or flare";• any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";• the statements in (and/or attached to) this, hereinafter "the statements in this";• and the past tense will be used in lieu of mixed past/present tense questions and statements. |
|--|

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 253667

QUESTIONS

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 253667 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

QUESTIONS

| | |
|--|--|
| Prerequisites Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions. | |
| Incident Well | Unavailable. |
| Incident Facility | [fAPP2215035840] Red Tank 27 28 Oil Gathering System |

| | |
|---|---|
| Determination of Reporting Requirements Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance. | |
| Was this vent or flare caused by an emergency or malfunction | No |
| Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event | Yes |
| Is this considered a submission for a vent or flare event | Yes, minor venting and/or flaring of natural gas. |
| An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC. | |
| Was there at least 50 MCF of natural gas vented and/or flared during this event | Yes |
| Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water | No |
| Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence | No |

| | |
|---|---|
| Equipment Involved | |
| Primary Equipment Involved | Other (Specify) |
| Additional details for Equipment Involved. Please specify | VCU Meter 151312 tracking combusted gas - No wells were involved with this flaring event as this event is due to combustion of storage tank vapors by an enclosed combustion device which is used routinely at this facility, pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%. |

| | |
|---|---------------|
| Representative Compositional Analysis of Vented or Flared Natural Gas Please provide the mole percent for the percentage questions in this group. | |
| Methane (CH4) percentage | 70 |
| Nitrogen (N2) percentage, if greater than one percent | 2 |
| Hydrogen Sulfide (H2S) PPM, rounded up | 3 |
| Carbon Dioxide (C02) percentage, if greater than one percent | 2 |
| Oxygen (O2) percentage, if greater than one percent | 0 |
| If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas. | |
| Methane (CH4) percentage quality requirement | Not answered. |
| Nitrogen (N2) percentage quality requirement | Not answered. |
| Hydrogen Sufide (H2S) PPM quality requirement | Not answered. |
| Carbon Dioxide (C02) percentage quality requirement | Not answered. |
| Oxygen (O2) percentage quality requirement | Not answered. |

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 253667

QUESTIONS (continued)

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 253667 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

QUESTIONS

| Date(s) and Time(s) | |
|--|------------|
| Date vent or flare was discovered or commenced | 08/07/2023 |
| Time vent or flare was discovered or commenced | 12:00 AM |
| Time vent or flare was terminated | 11:59 PM |
| Cumulative hours during this event | 24 |

| Measured or Estimated Volume of Vented or Flared Natural Gas | |
|---|---|
| Natural Gas Vented (Mcf) Details | Not answered. |
| Natural Gas Flared (Mcf) Details | Cause: Other Other (Specify) Natural Gas Flared Released: 64 Mcf Recovered: 0 Mcf Lost: 64 Mcf. |
| Other Released Details | Not answered. |
| Additional details for Measured or Estimated Volume(s). Please specify | VCU Meter 151312 tracking combusted gas |
| Is this a gas only submission (i.e. only significant Mcf values reported) | Yes, according to supplied volumes this appears to be a "gas only" report. |

| Venting or Flaring Resulting from Downstream Activity | |
|---|---------------|
| Was this vent or flare a result of downstream activity | No |
| Was notification of downstream activity received by this operator | Not answered. |
| Downstream OGRID that should have notified this operator | Not answered. |
| Date notified of downstream activity requiring this vent or flare | Not answered. |
| Time notified of downstream activity requiring this vent or flare | Not answered. |

| Steps and Actions to Prevent Waste | |
|--|---|
| For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. | True |
| Please explain reason for why this event was beyond this operator's control | On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%. |
| Steps taken to limit the duration and magnitude of vent or flare | On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%. |
| Corrective actions taken to eliminate the cause and reoccurrence of vent or flare | On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to |

Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 253667

ACKNOWLEDGMENTS

| | |
|--|----------------|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: |
| | 16696 |
| | Action Number: |
| | 253667 |
| Action Type: | |
| [C-129] Venting and/or Flaring (C-129) | |

ACKNOWLEDGMENTS

| | |
|-------------------------------------|---|
| <input checked="" type="checkbox"/> | I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC. |
| <input checked="" type="checkbox"/> | I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively. |
| <input checked="" type="checkbox"/> | I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act. |
| <input checked="" type="checkbox"/> | I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment. |
| <input checked="" type="checkbox"/> | I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations. |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 253667

CONDITIONS

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 253667 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

CONDITIONS

| Created By | Condition | Condition Date |
|---------------|--|----------------|
| shelbyschoepf | If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event. | 8/17/2023 |