AKM MEASUREMENT SERVICES,LLC. Natural Gas Analysis Report GPA 2172-09/API 14.5 Report with GPA 2145-16 Physical Properties

	Sample Information
Sample Name	CYPRESS 33 CTB A CHECK 1
Technician	ANTHONY DOMINGUEZ
Analyzer Make & Model	INFICON MICRO GC
Last Calibration/Validation Date	04-27-2023
Meter Number	18940C
Air temperature	67
Flow Rate (MCF/Day)	
Heat Tracing	HEATED HOSE & GASIFIER
Sample description/mtr name	CYPRESS 33 CTB A CHECK 1
Sampling Method	FILL & EMPTY
Operator	OCCIDENTAL PETROLEUM
State	NEW MEXICO
Region Name	PERMIAN_RESOURCES
Asset	NEW MEXICO
System	WEST
FLOC	OP-L3818-BT001
Sample Sub Type	GAS LIFT
Sample Name Type	WELL
Vendor	AKM MEASUREMENT
Cylinder #	1951
Sampled by	LUIS JIMENEZ
Sample date	4-21-2023
Analyzed date	4-27-2023
Method Name	C9
Injection Date	2023-04-27 23:44:20
Report Date	2023-04-27 23:48:29
EZReporter Configuration File	1-16-2023 OXY GPA C9+ H2S #2.cfgx
Source Data File	3ff6495a-c75c-4101-9c04-63a841182185
NGA Phys. Property Data Source	GPA Standard 2145-16 (FPS)
Data Source	INFICON Fusion Connector

Component Results

Component Name	Peak Area	Raw Amount	Response Factor	Norm Mole%	Gross HV (Dry) (BTU / Ideal cu.ft.)	Relative Gas Density (Dry)	GPM (Dry) (Gal. / 1000 cu.ft.)	
Nitrogen	17397.4	0.9871	0.00005674	0.9894	0.0	0.00957	0.109	
Methane	1059173.2	77.4074	0.00007308	77.5879	785.5	0.42976	13.201	
CO2	4202.7	0.1970	0.00004688	0.1975	0.0	0.00300	0.034	
Ethane	248621.4	11.3075	0.00004548	11.3339	201.0	0.11767	3.042	
H2S	0.0	0.0000	0.00000000	0.0000	0.0	0.00000	0.000	
Propane	166800.3	5.4260	0.00003253	5.4386	137.2	0.08280	1.504	
iso-butane	71935.8	0.8012	0.00001114	0.8030	26.2	0.01611	0.264	
n-Butane	168504.8	1.8576	0.00001102	1.8619	60.9	0.03736	0.589	
iso-pentane	48124.8	0.4669	0.00000970	0.4680	18.8	0.01166	0.172	
n-Pentane	57620.6	0.5452	0.00000946	0.5465	22.0	0.01361	0.199	
hexanes	51772.0	0.3896	0.00000752	0.3905	18.6	0.01162	0.161	
heptanes	38565.0	0.2360	0.00000612	0.2365	13.0	0.00818	0.110	
octanes	19285.0	0.1030	0.00000534	0.1033	6.5	0.00407	0.053	
nonanes+	8539.0	0.0429	0.00000503	0.0430	3.0	0.00190	0.024	
Total:		99.7674		100.0000	1292.6	0.74733	19.462	

Results Summary

Result	Dry	Sat.
Total Un-Normalized Mole%	99.7674	
Pressure Base (psia)	14.730	
Temperature Base (Deg. F)	60.00	
Flowing Temperature (Deg. F)	81.6	
Flowing Pressure (psia)	69.3	
Gross Heating Value (BTU / Ideal cu.ft.)	1292.6	1270.1
ele Gredat daing yaye 8\$18/2023 9:52:55 P	M 1297.6	1275.5

 Received by OCD: 8/18/2/023 9:45:09 PM
 Dry
 Sat.
 Page 2 of 8

 Relative Density (G), Real
 0.7499
 0.7480

Monitored Parameter Report

Parameter	Value	Lower Limit	Upper Limit	Status	
Total un-normalized amount	99.7674	97.0000	103.0000	Pass	

UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM

Facility: Cypress 33A CTB Flare Date: 08/03/2023

Duration of event: 3 Hours 29 minutes **MCF Flared:** 105

Start Time: 08:30 PM End Time: 11:59 PM

Cause: Emergency Flare > Planned Maintenance > Prevention Purging > Gas Lift Scrubber Dump Lines

Method of Flared Gas Measurement: Gas Flare Meter

1. Reason why this event was beyond Operator's control:

In this case, Lost Tank 18 CPF intermittently flared due to a planned maintenance work on the gas lift scrubber dump lines, in which the lines were purged to prevent oxygen ingress to the sales line. During every brief instance of flaring, Oxy production techs, who were on-site to assist, began to choke wells during this process to eliminate as much flaring as possible without causing too much harm to the processing equipment and wells.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. In this case, Lost Tank 18 CPF intermittently flared due to a planned maintenance work on the gas lift scrubber dump lines, in which the lines were purged to prevent oxygen ingress to the sales line. During every brief instance of flaring, Oxy production techs, who were on-site to assist, began to choke wells during this process to eliminate as much flaring as possible without causing too much harm to the processing equipment and wells.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in its action to eliminate the cause and recurrence of flaring during a planned maintenance repair, as there will be times where intermittent flaring shall occur as a safety measure for personnel, equipment and operations. The only actions that Oxy can take is to minimize emissions as much as possible during these planned equipment maintenance periods.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 254420

DEFINITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	254420
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- · venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 254420

Phone: (505) 476-3470 Fax: (505) 476-3462				
C	QUESTIONS			
Operator:		OGRID:		
OXY USA INC P.O. Box 4294		16696		
P.O. Box 4294 Houston, TX 772104294		Action Number: 254420		
		Action Type: [C-129] Venting and/or Flaring (C-129)		
QUESTIONS				
Prerequisites				
Any messages presented in this section, will prevent submission of this application. Please resolve	these issues before continuing w	vith the rest of the questions.		
Incident Well	Unavailable.	iavailable.		
Incident Facility	[fAPP2305250553] Cypre	ess 33 A CTB		
Determination of Reporting Requirements				
Answer all questions that apply. The Reason(s) statements are calculated based on your answers a	and may provide addional quidanc	e.		
Was this vent or flare caused by an emergency or malfunction	Yes			
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No			
Is this considered a submission for a vent or flare event	Yes, minor venting and/o	r flaring of natural gas		
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during	<u> </u>			
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes	ay be a major or minor release under 19.10.29.7 NWAO.		
Did this vent or flare result in the release of ANY liquids (not fully and/or completely	103			
flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No			
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No			
Equipment Involved				
Primary Equipment Involved	Other (Specify)			
Additional details for Equipment Involved. Please specify	Emergency Flare > Plann Lines	ed Maintenance > Prevention Purging > Gas Lift Scrubber Dump		
Description Operation of Manufacture				
Representative Compositional Analysis of Vented or Flared Natural Gas				
Please provide the mole percent for the percentage questions in this group. Methods (CHA) percentage	70			
Methane (CH4) percentage	78			
Nitrogen (N2) percentage, if greater than one percent	1			
Hydrogen Sulfide (H2S) PPM, rounded up	0			
Carbon Dioxide (C02) percentage, if greater than one percent	0			
Oxygen (02) percentage, if greater than one percent	0			
If you are venting and/or flaring because of Pipeline Specification, please provide the required spe	cifications for each gas.			
Methane (CH4) percentage quality requirement	Not answered.			
Nitrogen (N2) percentage quality requirement	Not answered.			
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.			
Carbon Dioxide (C02) percentage quality requirement	Not answered.			
Oxygen (02) percentage quality requirement	Not answered.			

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 254420

QUESTIONS (continued)	
	OCBID:

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	254420
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)		
Date vent or flare was discovered or commenced	08/03/2023	
Time vent or flare was discovered or commenced	08:30 PM	
Time vent or flare was terminated	11:59 PM	
Cumulative hours during this event	3	

asured or Estimated Volume of Vented or Flared Natural Gas			
Natural Gas Vented (Mcf) Details	Not answered.		
Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 105 Mcf Recovered: 0 Mcf Lost: 105 Mcf.		
Other Released Details	Not answered.		
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter		
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.		

Venting or Flaring Resulting from Downstream Activity			
Was this vent or flare a result of downstream activity	No		
Was notification of downstream activity received by this operator	Not answered.		
Downstream OGRID that should have notified this operator	Not answered.		
Date notified of downstream activity requiring this vent or flare	Not answered.		
Time notified of downstream activity requiring this vent or flare	Not answered.		

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	In this case, Lost Tank 18 CPF intermittently flared due to a planned maintenance work on the gas lift scrubber dump lines, in which the lines were purged to prevent oxygen ingress to the sales line. During every brief instance of flaring, Oxy production techs, who were on-site to assist, began to choke wells during this process to eliminate as much flaring as possible without causing too much harm to the processing equipment and wells.
Steps taken to limit the duration and magnitude of vent or flare	It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. In this case, Lost Tank 18 CPF intermittently flared due to a planned maintenance work on the gas lift scrubber dump lines, in which the lines were purged to prevent oxygen ingress to the sales line. During every brief instance of flaring, Oxy production techs, who were on-site to assist, began to choke wells during this process to eliminate as much flaring as possible without causing too much harm to the processing equipment and wells.
	Oxy is limited in its action to eliminate the cause and recurrence of flaring during a planned maintenance repair, as there will be times where intermittent flaring shall occur as a safety

Corrective actions taken to eliminate the cause and reoccurrence of vent or flare

measure for personnel, equipment and operations. The only actions that Oxy can take is to minimize emissions as much as possible during these planned equipment maintenance periods.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 254420

ACKNOWLEDGMENTS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	254420
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

V	I acknowledge that I am authorized to submit a Venting and/or Flaring (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
V	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
V	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 254420

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	254420
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/18/2023