

Certificate of Analysis

Number: 6030-23120311-001A

Artesia Laboratory 200 E Main St. Artesia, NM 88210 Phone 575-746-3481

Chandler Montgomery Occidental Petroleum 1502 W Commerce Dr. Carlsbad, NM 88220

Jan. 11, 2024

Field: PERMIAN RESOURCES Sampled By: JΕ Station Name: Sand Dunes CTB Check Sample Of: Gas

Spot Station Number: 17000C Sample Date: 12/28/2023 09:20

Station Location: OP-L0901-BT002 Sample Conditions: 88 psig, @ 68 °F Ambient: 31 °F 12/28/2023 09:20

Sample Point: Meter Effective Date: NEW_MEXICO 17996 MSCFD Formation: Flow Rate: County: Method: GPA-2261M

Well Name: CTB Cylinder No: 5030-01063

Type of Sample: : Spot-Cylinder Instrument: 70104251 (Inficon GC-MicroFusion)

Heat Trace Used: N/A Last Inst. Cal.: 01/09/2024 0:00 AM

Sampling Method: : Fill and Purge Analyzed: 01/09/2024 08:30:50 by EBH

Sampling Company: : OXY

Analytical Data

| Components | Un-normalized Mol % | Mol. % | Wt. % | GPM at 14.65 psia |
|------------------------|----------------------------------|------------|----------|----------------------|
| Hydrogen Sulfide | 0.0000 | 0.0000 | 0.0000 | |
| Nitrogen | 1.2725 | 1.3037 | 1.5990 | |
| Carbon Dioxide | 0.5710 | 0.5850 | 1.1272 | |
| Methane | 70.6744 | 72.4044 | 50.8552 | |
| Ethane | 12.9937 | 13.3118 | 17.5248 | 3.555 |
| Propane | 7.3509 | 7.5308 | 14.5390 | 2.072 |
| Iso-Butane | 0.8677 | 0.8889 | 2.2620 | 0.290 |
| n-Butane | 2.1166 | 2.1684 | 5.5180 | 0.683 |
| Iso-Pentane | 0.4679 | 0.4794 | 1.5143 | 0.175 |
| n-Pentane | 0.5187 | 0.5314 | 1.6786 | 0.192 |
| Hexanes | 0.3367 | 0.3449 | 1.3013 | 0.142 |
| Heptanes | 0.2976 | 0.3049 | 1.3376 | 0.140 |
| Octanes | 0.1258 | 0.1289 | 0.6447 | 0.066 |
| Nonanes Plus | 0.0170 | 0.0175 | 0.0983 | 0.010 |
| | 97.6105 | 100.0000 | 100.0000 | 7.325 |
| Calculated Physical | Properties | Tot | al | C9+ |
| Calculated Molecular \ | • | 22.8 | | 128.26 |
| Compressibility Factor | | 0.995 | | |
| Relative Density Real | | 0.791 | 17 | 4.4283 |
| GPA 2172 Calculation | | | | |
| Calculated Gross BT | U per ft ³ @ 14.65 ps | sia & 60°F | | |
| Real Gas Dry BTU | | 1340 | .5 | 6974.4 |
| Water Sat. Gas Base I | BTU | 1317 | .6 | 6852.4 |
| Ideal, Gross HV - Dry | at 14.65 psia | 1334 | .7 | 6974.4 |
| Ideal, Gross HV - Wet | | 1311 | .4 | 6852.4 |
| Comments: H2S Fie | ld Content 0 ppm | | | |

FMP/LSE NM40659

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality

assurance, unless otherwise stated.

VCU FLARING EVENT SPECIFIC JUSTIFICATIONS FORM

Facility: Sand Dunes SC CTB Date: 03/02/2024

Duration of event: >8 hours/day **MCF Flared:** 52

Start Time: 12:00 AM End Time: 11:59 PM

Cause: Routine Combustion of storage tank vapors using an enclosed combustion device (VCU)

Method of Flared Gas Measurement: SC CTB VCU 1 tracking combusted gas

Comments: No wells were involved with this flaring event as this event is due to combustion of storage tank vapors by an enclosed combustion device which is used routinely at this facility, pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

1. Reason why this event was beyond Operator's control:

On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

2. Steps Taken to limit duration and magnitude of venting or flaring:

On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that "... pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 322701

DEFINITIONS

| Operator: (| OGRID: |
|-----------------------|--|
| OXY USA INC | 16696 |
| P.O. Box 4294 | Action Number: |
| Houston, TX 772104294 | 322701 |
| | Action Type: |
| | [C-129] Venting and/or Flaring (C-129) |

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- · venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 322701

| <u>u</u> | UESTIONS | |
|--|---|--|
| Operator: OXY USA INC | OGRID: 16696 | |
| P.O. Box 4294 Houston, TX 772104294 | Action Number: 322701 | |
| | Action Type: [C-129] Venting and/or Flaring (C-129) | |
| QUESTIONS | | |
| Prerequisites | | |
| Any messages presented in this section, will prevent submission of this application. Please resolve | these issues before continuing with the rest of the questions. | |
| Incident Well | Unavailable. | |
| Incident Facility | [fAPP2127048458] Sand Dunes South Corridor CTB | |
| Determination of Reporting Requirements | | |
| Answer all questions that apply. The Reason(s) statements are calculated based on your answers a | nd may provide addional quidance | |
| Was this vent or flare caused by an emergency or malfunction | No | |
| Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event | Yes | |
| Is this considered a submission for a vent or flare event | Yes, minor venting and/or flaring of natural gas. | |
| An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during | renting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC. | |
| Was there at least 50 MCF of natural gas vented and/or flared during this event | Yes | |
| Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water | No | |
| Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence | No | |
| Equipment Involved | | |
| · · | | |
| Primary Equipment Involved | Other (Specify) | |
| Additional details for Equipment Involved. Please specify | SC CTB VCU 2 tracking combusted gas - No wells were involved with this flaring event as this event is due to combustion of storage tank vapors by an enclosed combustion device which is used routinely at this facility, pursuant to Federal US EPA NSPS OOO/OOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%. | |
| | - | |
| Representative Compositional Analysis of Vented or Flared Natural Gas | | |
| Please provide the mole percent for the percentage questions in this group. Methane (CH4) percentage | 72 | |
| Nitrogen (N2) percentage | 1 | |

| Please provide the mole percent for the percentage questions in this group. | | | |
|---|---------------|--|--|
| Methane (CH4) percentage | 72 | | |
| Nitrogen (N2) percentage, if greater than one percent | 1 | | |
| Hydrogen Sulfide (H2S) PPM, rounded up | 0 | | |
| Carbon Dioxide (C02) percentage, if greater than one percent | 1 | | |
| Oxygen (02) percentage, if greater than one percent | 0 | | |
| If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas. | | | |
| Methane (CH4) percentage quality requirement | Not answered. | | |
| Nitrogen (N2) percentage quality requirement | Not answered. | | |
| Hydrogen Sufide (H2S) PPM quality requirement | Not answered. | | |
| Carbon Dioxide (C02) percentage quality requirement | Not answered. | | |
| Oxygen (02) percentage quality requirement | Not answered. | | |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 **Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 322701

QUESTIONS (continued)

State of New Mexico

| 4020110110/0 | onanaoa, |
|-----------------------|--|
| Operator: | OGRID: |
| OXY USA INC | 16696 |
| P.O. Box 4294 | Action Number: |
| Houston, TX 772104294 | 322701 |
| | Action Type: |
| | [C-129] Venting and/or Flaring (C-129) |
| QUESTIONS | , |

| Date(s) and Time(s) | | |
|--|------------|--|
| Date vent or flare was discovered or commenced | 03/02/2024 | |
| Time vent or flare was discovered or commenced | 12:00 AM | |
| Time vent or flare was terminated | 11:59 PM | |
| Cumulative hours during this event | 24 | |

| Measured or Estimated Volume of Vented or Flared Natural Gas | | |
|---|---|--|
| Natural Gas Vented (Mcf) Details | Not answered. | |
| Natural Gas Flared (Mcf) Details | Cause: Other Other (Specify) Natural Gas Flared Released: 78 Mcf Recovered: 0 Mcf Lost: 78 Mcf. | |
| Other Released Details | Not answered. | |
| Additional details for Measured or Estimated Volume(s). Please specify | SC CTB VCU 2 tracking combusted gas | |
| Is this a gas only submission (i.e. only significant Mcf values reported) | Yes, according to supplied volumes this appears to be a "gas only" report. | |

| Venting or Flaring Resulting from Downstream Activity | | |
|---|---------------|--|
| Was this vent or flare a result of downstream activity | No | |
| Was notification of downstream activity received by this operator | Not answered. | |
| Downstream OGRID that should have notified this operator | Not answered. | |
| Date notified of downstream activity requiring this vent or flare | Not answered. | |
| Time notified of downstream activity requiring this vent or flare | Not answered. | |

| Steps and Actions to Prevent Waste | | |
|--|---|--|
| For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. | True | |
| Please explain reason for why this event was beyond this operator's control | On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that " pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%. | |
| Steps taken to limit the duration and magnitude of vent or flare | On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that " pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank vapors by this enclosed combustion device is used routinely at this facility pursuant to Federal US EPA NSPS OOOO/OOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%. | |
| Corrective actions taken to eliminate the cause and reoccurrence of vent or flare | On May 17, 2021, NMOCD issued a notice entitled, "Frequently Asked Questions Regarding the Natural Gas Waste Rules," and states that " pursuant to 19.15.27.8(G) NMAC, an operator who vents or flares for any reason and that lasts more than 8 hours cumulatively during any 24-hour period must report that event on Form C-129." Combustion of storage tank yapors by this enclosed combustion device is used routinely at this facility pursuant to | |

Federal US EPA NSPS OOOO/OOOOa regulations and state air permitting requirements that require the use of such a device to reduce storage tank emissions by 95%.

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 322701

ACKNOWLEDGMENTS

| Operator: | OGRID: |
|-----------------------|--|
| OXY USA INC | 16696 |
| P.O. Box 4294 | Action Number: |
| Houston, TX 772104294 | 322701 |
| | Action Type: |
| | [C-129] Venting and/or Flaring (C-129) |

ACKNOWLEDGMENTS

| > | I acknowledge that I am authorized to submit a Venting and/or Flaring (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC. |
|-------------|---|
| V | I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively. |
| V | I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act. |
| V | I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment. |
| ~ | I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations. |

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 322701

CONDITIONS

| Operator: | OGRID: |
|-----------------------|--|
| OXY USA INC | 16696 |
| P.O. Box 4294 | Action Number: |
| Houston, TX 772104294 | 322701 |
| | Action Type: |
| | [C-129] Venting and/or Flaring (C-129) |

CONDITIONS

| Created By | | Condition Date |
|---------------|--|-------------------|
| shelbyschoepf | If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event. | 3/12/2024 |