Cons.	PAW BBLS OIL BBLS FAW BBLS	TOP GAUGE BOTTOM GAUGE	COMPANY LOCATION WORK TYPE	DATE_DS/24/24 TRUCK	
U WENT COMPANY MAN		Callegt a Spill transfer poins unlocated at MI	CONTON 21 CA	P.O. Box 878 Carlsbad, NM 88221 Office: 575-887-5827	
Z	TAX	o comal	В	432-664-4668 Email: jesus@testrucking.com melissa@testrucking.com	
PRINT BY DESIGN	TAX		TNUOMA	WATER TICKET No. 0003158	

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 350443

QUESTIONS

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	350443
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2415550610	
Incident Name	NAPP2415550610 CORRAL CANYON 21 CVB @ 0	
Incident Type	Oil Release	
Incident Status	Initial C-141 Received	

Location of Release Source		
Please answer all the questions in this group.		
Site Name	Corral Canyon 21 CVB	
Date Release Discovered	05/24/2024	
Surface Owner	State	

Incident Details		
Please answer all the questions in this group.		
Incident Type	Oil Release	
Did this release result in a fire or is the result of a fire	No	
Did this release result in any injuries	No	
Has this release reached or does it have a reasonable probability of reaching a watercourse	No	
Has this release endangered or does it have a reasonable probability of endangering public health	No	
Has this release substantially damaged or will it substantially damage property or the environment	No	
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No	

Nature and Volume of Release		
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.		
Crude Oil Released (bbls) Details	Cause: Equipment Failure Pump Crude Oil Released: 20 BBL Recovered: 20 BBL Lost: 0 BBL.	
Produced Water Released (bbls) Details	Not answered.	
Is the concentration of chloride in the produced water >10,000 mg/l	No	
Condensate Released (bbls) Details	Not answered.	
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Not answered.	
Other Released Details	Not answered.	
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Not answered.	

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 350443

QUESTIONS (continued)		
ator:	OGRID:	
XTO ENERGY, INC	5380	
6401 Holiday Hill Road	Action Number:	
Midland, TX 79707	350443	

Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Ope

Nature and Volume of Release (continued)			
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.		
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	No		
Reasons why this would be considered a submission for a notification of a major release	Unavailable.		
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.			

nitial Response			
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.			
The source of the release has been stopped	True		
The impacted area has been secured to protect human health and the environment	True		
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True		
All free liquids and recoverable materials have been removed and managed appropriately	True		
If all the actions described above have not been undertaken, explain why	Not answered.		

Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Name: Alan Romero

Title: Regulatory Analyst
Email: alan.romero1@exxonmobil.com

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 350443

QUESTIONS (con	tinuea)
----------------	---------

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	350443
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Site Characterization			
Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.			
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Not answered.		
What method was used to determine the depth to ground water	Not answered.		
Did this release impact groundwater or surface water	Not answered.		
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:			
A continuously flowing watercourse or any other significant watercourse	Not answered.		
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Not answered.		
An occupied permanent residence, school, hospital, institution, or church	Not answered.		
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Not answered.		
Any other fresh water well or spring	Not answered.		
Incorporated municipal boundaries or a defined municipal fresh water well field	Not answered.		
A wetland	Not answered.		
A subsurface mine	Not answered.		
An (non-karst) unstable area	Not answered.		
Categorize the risk of this well / site being in a karst geology	Not answered.		
A 100-year floodplain	Not answered.		
Did the release impact areas not on an exploration, development, production, or storage site	Not answered.		

Remediation Plan			
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.			
Requesting a remediation plan approval with this submission	No		
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 350443

CONDITIONS

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	350443
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	6/3/2024