

Site Name	Lattion Pit
Location	O-23-18S-26E; Eddy County, NM
Incident ID	NAUTOFAB000337
Source & Description of Activities	Groundwater Sampling
Expected Duration for Activities	Week of 12/09/2024
Env Consultant	Ranger Environmental Services, LLC
	Yes - Starting Tuesday, 12/10/2024 @ 0800
	4 samples
Sampling Notification Required	NMOCD Mr. Mike Buchanan (Michael.Buchanan@emnrd.nm.gov)
Sample Number	4
Driving Directions	Directions to the site can be provided after an email request
Sampler Information	Chase Settle 575-703-6537 chase_settle@eogresources.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 406832

CONDITIONS

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 406832
	Action Type: [UF-GWA] Ground Water Abatement (GROUND WATER ABATEMENT)

CONDITIONS

Created By	Condition	Condition Date
michael.buchanan	Groundwater sampling notification received on 11/26/2024 for the Lattion Pit, sampling for the site to be conducted, Tuesday, 12/10/2024 @ 0800 4 samples. App ID: 406832	11/26/2024