Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 424769

QUESTIONS

| ı | Operator: | OGRID: |
|---|-------------------------------------|--|
| ı | DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| ı | 333 West Sheridan Ave. | Action Number: |
| ı | Oklahoma City, OK 73102 | 424769 |
| ı | | Action Type: |
| ı | | [NOTIFY] Notification Of Liner Inspection (C-141L) |

QUESTIONS

| Prerequisites | | |
|-------------------|------------------------------------|--|
| Incident ID (n#) | nAPP2435652226 | |
| Incident Name | NAPP2435652226 JAYHAWK 7 CTB 2 @ 0 | |
| Incident Type | Produced Water Release | |
| Incident Status | Initial C-141 Approved | |
| Incident Facility | [fAPP2130256650] JAYHAWK 7 CTB 2 | |

| ocation of Release Source | |
|---------------------------|-----------------|
| Site Name | JAYHAWK 7 CTB 2 |
| Date Release Discovered | 12/21/2024 |
| Surface Owner | Federal |

| Liner Inspection Event Information | | | | |
|---|--|--|--|--|
| Please answer all the questions in this group. | | | | |
| What is the liner inspection surface area in square feet | 7,356 | | | |
| Have all the impacted materials been removed from the liner | Yes | | | |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 01/30/2025 | | | |
| Time liner inspection will commence | 12:30 AM | | | |
| Please provide any information necessary for observers to liner inspection | Monica Peppin 575.909.3418 | | | |
| Please provide any information necessary for navigation to liner inspection site | Intersection of 128/Battle Axe Rd travel south on Battle Axe 12.3 miles, turn left onto lease road travel 0.07 miles, turn left on Anthony Rd travel 1.3 miles, turn right 0.07 miles, at Y stay right, continue on lease rd and follow onto location. 32.06140013, -103.5114962 | | | |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 424769

CONDITIONS

| Operator: | OGRID: |
|-------------------------------------|--|
| DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| 333 West Sheridan Ave. | Action Number: |
| Oklahoma City, OK 73102 | 424769 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Create By | | Condition Date |
|--------------|--|-------------------|
| jrale | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 1/27/2025 |