



C9+ Analysis

GPA 2172-19/API 14.5 Report with GPA 2145-16 Physical Properties

Sample Information

	Sample Information
Sample Name	SATELLITE GAS SALES
Operator	Franklin Mountain Energy
Lease	SATELLITE GAS SALES
PA#	
CA#	
Sample Date/Time:	11-20-24 9:45 AM
Effective Date	
Laboratory	Laboratory Services and Measurement
Technician	AGILENT MICRO GC 3000
Analyzer Type	Gas Chromatograph - TCD
Analyzer Make & Model	Agilent Micro GC 3000
Last Calibration/Validation Date	11-25-24
Sample Temperature	81 F
Sample Pressure	121 PSI
Sample Flow Rate	4763 MCF
Ambient Temperature	44 F
Heat Tracing	No
Sample Type	Spot
Sampling Method	Fill and Purge
Company Collecting Sample	Blackhawk Measurement Consulting
Sampled By	HM
Cylinder #	1998
Mole, Weight, or Percent (For Flowcal DON'T EDIT)	M
Sample Calculation Method(For Flowcal DON'T EDIT)	GPA 2172/API 14.5 Report with GPA 2145 Physical Properties
Date Reported	2024-11-25 10:45:21

Component Results

Component Name	Un-Normalized Mole%	Norm Mole%	GPM (Dry) (Gal. / 1000 cu.ft.)	GPM (Sat) (Gal. / 1000 cu.ft.)	
Nitrogen	3.4770	3.4710	0.000	0.000	
Carbon Dioxide	1.2890	1.2868	0.000	0.000	
Methane	58.8740	58.7717	0.000	0.000	
Ethane	16.7590	16.7299	4.473	4.397	

Component Name	Un-Normalized Mole%	Norm Mole%	GPM (Dry) (Gal. / 1000 cu.ft.)	GPM (Sat) (Gal. / 1000 cu.ft.)	
Propane	12.3290	12.3076	3.390	3.332	
isobutane	1.3090	1.3067	0.428	0.420	
n-Butane	3.6060	3.5997	1.135	1.115	
isopentane	0.7860	0.7846	0.287	0.282	
n-Pentane	0.7300	0.7287	0.264	0.260	
hexanes	0.6170	0.6159	0.253	0.249	
heptanes	0.2010	0.2007	0.093	0.091	
octanes	0.0230	0.0230	0.012	0.012	
nonanes+	0.0040	0.0040	0.002	0.002	
hydrogen sulfide	0.1700	0.1697	0.023	0.023	
Total:	100.1740	100.0000	10.359	10.283	

Results Summary

Result	Dry	Wet/Sat	
Total Un-Normalized Mole%	100.1740		
Pressure Base (psia)	14.650		
Temperature Base (Deg. F)	60.00		
Gross Heating Value (BTU / Ideal cu.ft.)	1458.4	1432.9	
Gross Heating Value (BTU / Real cu.ft.)	1466.5	1441.5	
Relative Density (G), Ideal	0.9042	0.8993	
Relative Density (G), Real	0.9089	0.9043	
Compressibility (Z) Factor	0.9945	0.9940	
Total GPM	10.359	10.283	

Facility ID	
	fAPP2432430117 - Satellite/Cross CTB
Date/Time Flaring/Venting Began:	
	2025-01-26 00:01:00
Date/Time Flaring/Venting Ended:	
	2025-01-26 23:59:00
Cumulative Hours Of Event:	
	22.42
Total (MCF)	
	3668.97
Index	
	3481

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 424834

DEFINITIONS

Operator: Franklin Mountain Energy 3, LLC 44 Cook Street Denver, CO 80206	OGRID: 331595
	Action Number: 424834
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 424834

QUESTIONS

Operator: Franklin Mountain Energy 3, LLC 44 Cook Street Denver, CO 80206	OGRID: 331595
	Action Number: 424834
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	Unavailable.
Incident Facility	[fAPP2432430117] Satellite/Cross CTB

Determination of Reporting Requirements <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a vent or flare event	Yes, major venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas <i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	58
Nitrogen (N2) percentage, if greater than one percent	3
Hydrogen Sulfide (H2S) PPM, rounded up	1,697
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 424834

QUESTIONS (continued)

Operator: Franklin Mountain Energy 3, LLC 44 Cook Street Denver, CO 80206	OGRID: 331595
	Action Number: 424834
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	01/26/2025
Time vent or flare was discovered or commenced	12:01 AM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	22

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Gas Plant Natural Gas Flared Released: 3,668 Mcf Recovered: 0 Mcf Lost: 3,668 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	Yes
Was notification of downstream activity received by this operator	No
Downstream OGRID that should have notified this operator	[331501] Northwind Midstream Partners LLC
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	Northwind Titan plant down for plant issues
Steps taken to limit the duration and magnitude of vent or flare	Swing volumes to available systems
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Regular group chat with Northwind area representatives to monitor, discuss, and alert

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 424834

ACKNOWLEDGMENTS

Operator: Franklin Mountain Energy 3, LLC 44 Cook Street Denver, CO 80206	OGRID: 331595
	Action Number: 424834
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 424834

CONDITIONS

Operator: Franklin Mountain Energy 3, LLC 44 Cook Street Denver, CO 80206	OGRID: 331595
	Action Number: 424834
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
ygelfand	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	1/27/2025