

www.permianls.com 575.397.3713 2609 W MARLAND HOBBS, NEW MEXICO 88240

EXTENDED GAS REPORT SUMMARY OF CHROMATOGRAPHIC ANALYSIS

Sample Name: Wild Hog Compressor Station

10/31/2024

Cyl. Ident.: Targa

For:

22711G 2024100570

Sample Date: Sampled By:

Alexis Vasquez

Company: **Analysis Date:**

11/07/2024

Time Sampled: Sample Temp:

11:50 60.0 F

Analysis By:

LC

Sample Press:

32.0

H2S (PPM) = 1600.0

Data File: LS1_0969.D

Component	Mole%	GPM REAL	GPM IDEAL
H2S	0.160		
Nitrogen	0.973		
Methane	79.849		
CO2	2.886		
Ethane	7.024	1.878	1.874
Propane	3.493	0.962	0.960
Isobutane	0.830	0.272	0.271
N-Butane	1.613	0.508	0.507
Isopentane	0.716	0.262	0.261
N-Pentane	0.592	0.215	0.214
Hexanes+	1.864	0.892	0.890
Total	100.000	4.989	4.977

CALCULATED PARAMETERS

TOTAL ANALYSIS SUMMARY		HEATING VAL	BTEX SUMMARY	
MOLE WT: VAPOR PRESS PSIA: SPECIFIC GRAV	22.637 4056.9	BTU/CUFT (DRY) BTU/CUFT (WET)	1275.0 1253.4	WT% BENZENE 13.379 WT% TOLUENE 0.000 WT% E BENZENE 0.192
AIR = 1 (REAL): AIR = 1 (IDEAL): H2O = 1 (IDEAL):	0.7822 0.7795 0.374			WT% XYLENES 0.624
REPORTED BASIS: Unnormalized Total:	14.73 134.888		-	LAB MANAGER

Constants: GPA 2145 Method: GPA 2186.m Report Rev 18-05.22 Template: eC6+ Liq



www.permianls.com 575.397.3713 2609 W MARLAND HOBBS, NEW MEXICO 88240

Sample Name: Wild Hog Compressor Station Data File: LS1_0969.D

Company: Targa

*ANALYSIS OF HEXANES PLUS

Component	MOLE%	WT%	*HEXANES PLUS SUMMARY
2,2 DIMETHYL BUTANE	0.005	0.018	AVG MOLE WT 118.754
CYCLOPENTANE	0.003	0.011	VAPOR PRESS PSIA 9.860
2-METHYLPENTANE	0.002	0.009	API GRAVITY @ 60F 49.4
3-METHYLPENTANE	0.002	0.009	SPECIFIC GRAVITY
HEXANE (C6)	0.002	0.009	AIR = 1 (IDEAL): 2.975
DIMETHYLPENTANES	0.013	0.056	H2O = 1 (IDEAL): 0.782
METHYLCYCLOPENTANE	0.002	0.007	
2,2,3 TRIMETHYLBUTANE	0.000	0.000	
BENZENE	0.002	0.006	
CYCLOHEXANE	0.003	0.010	COMPONENT RATIOS
2-METHYLHEXANE	0.019	0.084	
3-METHYLHEXANE	0.033	0.146	HEXANES (C6) MOLE% 0.798
DIMETHYCYCLOPENTANES	0.000	0.000	HEPTANES (C7) MOLE% 4.935
HEPTANE (C7)	0.001	0.005	OCTANES (C8) MOLE% 8.076
METHYLCYCLOHEXANE	0.004	0.016	NONANES (C9) MOLE% 60.971
2,5 DIMETHYLHEXANE	0.006	0.030	DECANES+ (C10+) MOLE% 25.220
TOLUENE	0.000	0.000	
2-METHYLHEPTANE	0.022	0.109	
OTHER OCTANES	0.117	0.600	HEXANES (C6) WT% 0.568
OCTANE (C8)	0.002	0.008	HEPTANES (C7) WT% 4.131
ETHYLCYCLOHEXANE	0.003	0.015	OCTANES (C8) WT% 7.813
ETHYL BENZENE	0.004	0.018	NONANES (C9) WT% 58.259
M,P-XYLENE	0.006	0.029	DECANES+ (C10+) WT% 29.229
O-XYLENE	0.007	0.031	
OTHER NONANES	1.114	5.589	
NONANE (C-9)	0.003	0.018	
IC3 BENZENE	0.008	0.040	
CYCLOOCTANE	0.070	0.368	
NC3 BENZENE	0.001	0.007	
TM BENZENE(S)	0.006	0.034	
IC4 BENZENE	0.003	0.017	
NC4 BENZENE	0.009	0.053	
DECANES + (C10+)	0.373	2.339	



ARGA NDL Blowdown/Vent Estimate

All sections should be filled out by field personnel. All red fields per event must be entered to calculate volumes correctly! All yellow fields should be entered if known for increased accuracy.

Date of Ocurrance (m/d/yyyy)		2/8/2025	Reported By (First and Last Name)	Willie Pierce	
Site (Select) CS - WILD HOG			If "FIELD" for Site, Pipe Name	Winkler 10"	
			Lat	32.0339964	
			Long	-103.2885419	

	Calculated Volumes					
Blowdown(s)				Purge/Vent		
Reference Meter Number		Blowdown (MCF)	1,571.68	Reference Meter Number	Volume Lost (MCF)	
Pipe ID (in)	10in Sch. 80	Length (Feet)	46,560.00	Beginning Date & Time	Vent Duration (Hours)	
Begin Press. (PSIG)	1,072.00	End Press. (PSIG)	322.00	Ending Date & Time	Gas Temp	
Gas Temp.		Specific Gravity		Pipe ID (in)	Specific Gravity	
Elevation (ft)				Orifice Size (in)	Elevation (ft)	
Beginning Date & Time	02/08/2025 1127	Ending Date & Time	02/08/2025 2359	Avg Pressure		
Reference Meter Number		Blowdown (MCF)		Reference Meter Number	Volume Lost (MCF)	
Pipe ID (in)		Length (Feet)		Beginning Date & Time	Vent Duration (Hours)	
Begin Press. (PSIG)		End Press. (PSIG)		Ending Date & Time	Gas Temp	
Gas Temp.		Specific Gravity		Pipe ID (in)	Specific Gravity	
Elevation (ft)				Orifice Size (in)	Elevation (ft)	
Beginning Date & Time		Ending Date & Time		Avg Pressure		
Reference Meter Number		Blowdown (MCF)		Reference Meter Number	Volume Lost (MCF)	
Pipe ID (in)		Length (Feet)		Beginning Date & Time	Vent Duration (Hours)	
Begin Press. (PSIG)		End Press. (PSIG)		Ending Date & Time	Gas Temp	
Gas Temp.		Specific Gravity		Pipe ID (in)	Specific Gravity	
Elevation (ft)				Orifice Size (in)	Elevation (ft)	
Beginning Date & Time		Ending Date & Time		Avg Pressure		

Comments:

2/8/2025 We blew down the Winkler 10" to remove a hydrate. It was blown down through a remote flare setup with a three phase seperator. All the liquids collected were offloaded at the Wildhog station. Once the line pressure reached 322psi the hydrate broke loose and we controlled the flow of liquid.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

DEFINITIONS

Action 434148

DEFINITIONS

Operator:	OGRID:
Targa Northern Delaware, LLC.	331548
110 W. 7th Street, Suite 2300	Action Number:
Tulsa, OK 74119	434148
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116

Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 434148

QI	JESTIONS	
Operator:		OGRID:
Targa Northern Delaware, LLC. 110 W. 7th Street, Suite 2300		331548 Action Number:
Tulsa, OK 74119		434148
		Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve t	hese issues before continuing with	h the rest of the questions.
Incident Well	Unavailable.	
Incident Facility	[fAPP2123031392] TARGA	NORTHERN DELAWARE, LLC.
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers ar		
Was this vent or flare caused by an emergency or malfunction	Yes	
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes	
Is this considered a submission for a vent or flare event	Yes, major venting and/or	flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v	enting and/or flaring that is or may	be a major or minor release under 19.15.29.7 NMAC.
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes	
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Equipment Involved		
Primary Equipment Involved	Not answered.	
1 Timery Equipment involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	80	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	1,600	
Carbon Dioxide (C02) percentage, if greater than one percent	3	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specification, please provide the required specification, please provide the required specification.		
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 434148

OHESTI	ONS (continued)
Operator:	OGRID:
Targa Northern Delaware, LLC.	331548
110 W. 7th Street, Suite 2300 Tulsa, OK 74119	Action Number: 434148
·	Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS	[O-129] Venting and/or Framing (O-129)
Date(s) and Time(s)	
Date vent or flare was discovered or commenced	02/08/2024
Time vent or flare was discovered or commenced	11:27 AM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	13
Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Freeze Gas Compressor Station Natural Gas Flared Released: 1,572 Mcf
Other Released Details	Recovered: 0 Mcf Lost: 1,572 Mcf. Not answered.
Other released Betalis	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.
Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	
I	Not answered.
Downstream OGRID that should have notified this operator	Not answered. Not answered.
Downstream OGRID that should have notified this operator Date notified of downstream activity requiring this vent or flare	
·	Not answered.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare	Not answered. Not answered.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste	Not answered. Not answered.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare	Not answered. Not answered.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event	Not answered. Not answered. Not answered.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event	Not answered. Not answered. True
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. Please explain reason for why this event was beyond this operator's control	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect personnel and equipment.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. Please explain reason for why this event was beyond this operator's control	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect personnel and equipment.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. Please explain reason for why this event was beyond this operator's control	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect personnel and equipment.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. Please explain reason for why this event was beyond this operator's control	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect personnel and equipment.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. Please explain reason for why this event was beyond this operator's control	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect personnel and equipment. Gas was flared until the obstruction was removed. The obstruction was removed, and the emission event ended. After the end of the event, the
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare Steps and Actions to Prevent Waste For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. Please explain reason for why this event was beyond this operator's control Steps taken to limit the duration and magnitude of vent or flare	Not answered. Not answered. True Gas was routed to a portable flare to remove an obstruction in the Winkler 10-inch inlet pipeline into the facility. It was necessary to route the pipeline blowdown to flare to protect personnel and equipment. Gas was flared until the obstruction was removed.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 434148

ACKNOWLEDGMENTS

	Operator:	OGRID:
ı	Targa Northern Delaware, LLC.	331548
ı	110 W. 7th Street, Suite 2300	Action Number:
ı	Tulsa, OK 74119	434148
ı		Action Type:
		[C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

V	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
V	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
V	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 434148

CONDITIONS

Operator:	OGRID:
Targa Northern Delaware, LLC.	331548
110 W. 7th Street, Suite 2300	Action Number:
Tulsa, OK 74119	434148
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created B	y Condition	Condition Date
tillmana	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	2/21/2025