Site Name	Lattion Pit
Location	0-23-18S-26E; Eddy County, NM
Incident ID	NAUTOFAB000337
Source & Description of Activities	Groundwater Sampling
Expected Duration for Activities	Week of 03/10/2025
Env Consultant	Ranger Environmental Services, LLC
Contractor	NA
C-138 Requested	No
Sampling Notification Required	Yes - Starting Tuesday 03/11/2025 @ 0800 4 samples (NMOCD District II, NMOCD Reps Mr. Nelson Velez (<u>nelson.velez@emnrd.nm.gov</u>) and Mr. Mike Buchanan (<u>Michael.Buchanan@emnrd.nm.gov</u>)
Core Rig Boring	No

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS		
EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377	
	Action Number: 435308	
	Action Type:	

[UF-GWA] Ground Water Abatement (GROUND WATER ABATEMENT)

CONDITIONS

Operator:

Created By	Condition	Condition Date
michael.buchanan	None	3/3/2025

ormation 5) 629-6116 Page 2 of 2

CONDITIONS

Action 435308