Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 440730

QUESTIONS

Operator:	OGRID:
CIMAREX ENERGY CO.	215099
6001 Deauville Blvd	Action Number:
Midland, TX 79706	440730
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2505545126	
Incident Name	NAPP2505545126 WHITE CITY 8 17-20 FED COM 2H @ 0	
Incident Type	Other	
Incident Status	Initial C-141 Approved	
Incident Facility	[fAPP2433124017] WHITE CITY 8-17-20 FED COM FACILITY	

Location of Release Source	
Site Name	White City 8 17-20 Fed Com 2H
Date Release Discovered	02/24/2025
Surface Owner	Federal

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	3,715			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	03/12/2025			
Time liner inspection will commence	11:30 AM			
Please provide any information necessary for observers to liner inspection	na			
Please provide any information necessary for navigation to liner inspection site	na			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 440730

CONDITIONS

Operator:	OGRID:
CIMAREX ENERGY CO.	215099
6001 Deauville Blvd	Action Number:
Midland, TX 79706	440730
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Cre By	ated	Condition	Condition Date
nr	ose	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	3/10/2025