Listed below are the volume calculations that were determined for this flare event:

	Information	Volumes	Methodology
A.	Flare Volume:	203	Gas Volume Field Personnel Repo
B.	CO2 Percentage:	94.07%	Gas Analysis – Nov -2024
C.	Hydrocarbon Percentage:	5.93%	Gas Analysis – Nov 2024
D.	Hydrocarbon Volume:	12	(1-co2 mol%) /100 * total volus
E.	CO2 Volume:	191	(co2 mol%)/100) * total volun

^{**} Gas analysis sample is current and within one year from date of event.

orted

me

ne

Pantechs Laboratories, Inc. - Order: 4617-7523 - 11/14/2024 - North Hobbs Unit - Compressor Suction and Discharge Samples at North Hobbs Batteries

SAMPLE ID		COLLECTION DATA		
Operator	Occidental Permian Ltd.	Pressure	28 psig	
Location	North Hobbs Unit	Sample Temp	64 F	
Site	North Injection Battery	Atm Temp	65 F	
Site Type	Battery	Collection Date	11/14/2024	
Sample Point	4500 Compressor Suction	Collection Time	10:21 AM	
Spot/Comp	Spot	Collection By	Cody Carson	
Meter ID		Pressure Base	14.650 psi	
Regulatory ID		Temperature Base	60 F	
Fluid	Gas	Container(s)	PL2393	

GPA 2261-20 Gas Fractional Analysis

COMPOUND	FORMULA	MOL%	WT%	GPM
NITROGEN	N2	0.090	0.056	0.010
CARBON DIOXIDE	CO2	94.065	92.322	16.053
HYDROGEN SULFIDE	H2S	0.832	0.632	0.112
METHANE	C1	0.282	0.101	0.048
ETHANE	C2	0.206	0.138	0.055
PROPANE	C3	0.914	0.899	0.252
I-BUTANE	iC4	0.366	0.474	0.120
N-BUTANE	nC4	1.093	1.417	0.345
I-PENTANE	iC5	0.601	0.967	0.220
N-PENTANE	nC5	0.550	0.885	0.199
HEXANES PLUS	C6+	1.001	2.109	0.427
TOTALS:		100.000	100.000	17.841

Value of "0.000" in fractional interpreted as below detectable limit. Onsite H2S value is used in fractional table if performed.

LIQUID YIELD	C2+	C3+	C4+	C5+	26# Liquid	10# Liquid
GAL/MSCF (GPM)	1.618	1.563	1.311	0.846	1.253	0.799

GPA 2172/ASTM D3588 CALCULATED PROPERTIES

WATER CONTENT	BTU/CF, Gross	BTU/CF, Net	Specific Gr.	Z Factor	Mol Weight	Wobbe IDX
DRY	180.80	167.62	1.558	0.993	44.841	144.84
SATURATED	178.60	164.69	1.543	0.993	44.058	

Onsite Testing by Stain Tube

METHOD	ТҮРЕ	MOL%	GRAINS/100	PPMV	LB/MMSCF
GPA2377	hydrogen sulfide	0.8321	528.36	8,400.9	396.2

Mol%, Grains/100, PPMV are pressure and temperature corrected to base conditions.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 445488

QUESTIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	445488
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites				
Incident ID (n#)	nAPP2507942928			
Incident Name	NAPP2507942928 NORTH HOBBS NIB @ 0			
Incident Type	Other			
Incident Status	Initial C-141 Approved			
Incident Facility	[fKJ1518128159] North Hobbs Unit NIB			

Location of Release Source			
Please answer all the questions in this group.			
Site Name	NORTH HOBBS NIB		
Date Release Discovered	02/14/2025		
Surface Owner	Private		

Incident Details			
Please answer all the questions in this group.			
Incident Type	Other		
Did this release result in a fire or is the result of a fire	No		
Did this release result in any injuries	No		
Has this release reached or does it have a reasonable probability of reaching a watercourse	No		
Has this release endangered or does it have a reasonable probability of endangering public health	No		
Has this release substantially damaged or will it substantially damage property or the environment	No		
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No		

Nature and Volume of Release				
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.				
Crude Oil Released (bbls) Details	Not answered.			
Produced Water Released (bbls) Details	Not answered.			
Is the concentration of chloride in the produced water >10,000 mg/l	No			
Condensate Released (bbls) Details	Not answered.			
Natural Gas Vented (Mcf) Details	Not answered.			
Natural Gas Flared (Mcf) Details	Cause: Downhole Well Maintenance Gas Compressor Station Natural Gas Flared Released: 12 MCF Recovered: 0 MCF Lost: 12 MCF.			
Other Released Details	Cause: Equipment Failure Gas Compressor Station Carbon Dioxide Released: 191 MCF Recovered: 0 MCF Lost: 191 MCF.			
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Not answered.			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 445488

QUESTIONS (continued)

QUEST	iONS (continued)	
Operator:		OGRID:
OCCIDENTAL PERMIAN LTD P.O. Box 4294		157984
Houston, TX 772104294		Action Number: 445488
		Action Type: [C-141] Initial C-141 (C-141-v-Initial)
QUESTIONS		
Nature and Volume of Release (continued)		
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied v	olumes this appears to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	No	
Reasons why this would be considered a submission for a notification of a major release	Unavailable.	
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.	e. gas only) are to be submitted on th	e C-129 form.
Initial Response		
The responsible party must undertake the following actions immediately unless they could create a s	safety hazard that would result in inju	ry.
The source of the release has been stopped	True	
The impacted area has been secured to protect human health and the environment	True	
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True	
All free liquids and recoverable materials have been removed and managed appropriately	True	
If all the actions described above have not been undertaken, explain why physical remedial actions w water, or environment, in or		ly. There was no liquid or fluid impact to the area and/or re necessary or required for the soil, groundwater, surface round the flare area as nothing occurred on the ground as there nent, or spillage of liquids or fluids during this event.
Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remed actions to date in the follow-up C-141 submission. If remedial efforts have been successfully comple Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure e	ted or if the release occurred within a	lined containment area (see Subparagraph (a) of Paragraph (5) of
I hereby certify that the information given above is true and complete to the best of my to report and/or file certain release notifications and perform corrective actions for release the OCD does not relieve the operator of liability should their operations have failed to water, human health or the environment. In addition, OCD acceptance of a C-141 report local laws and/or regulations.	ases which may endanger public adequately investigate and reme	chealth or the environment. The acceptance of a C-141 report by ediate contamination that pose a threat to groundwater, surface
I hereby agree and sign off to the above statement I hereby agree and sign off to the above statement Email: Shaina_rojas@oxy.com Date: 03/27/2025		

Sante Fe Main Office Phone: (505) 476-3441

storage site

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 3

Action 445488

QUESTIONS (continued)

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	445488
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS Site Characterization Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the What is the shallowest depth to groundwater beneath the area affected by the Not answered. release in feet below ground surface (ft bgs) What method was used to determine the depth to ground water Not answered. Did this release impact groundwater or surface water Not answered What is the minimum distance, between the closest lateral extents of the release and the following surface areas: A continuously flowing watercourse or any other significant watercourse Not answered Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) Not answered. An occupied permanent residence, school, hospital, institution, or church Not answered. A spring or a private domestic fresh water well used by less than five households Not answered. for domestic or stock watering purposes Any other fresh water well or spring Not answered. Incorporated municipal boundaries or a defined municipal fresh water well field Not answered. Not answered. A subsurface mine Not answered. An (non-karst) unstable area Not answered. Categorize the risk of this well / site being in a karst geology A 100-year floodplain Not answered. Did the release impact areas not on an exploration, development, production, or

Remediation Plan			
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.			
Requesting a remediation plan approval with this submission	No		
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in acco	ordance with the physical realities encountered during remediation. If the responsible party has any need to		

Not answered.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 445488

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	445488
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Crea	ited By		Condition Date
am	axwell	None	3/27/2025