Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 448887

QUESTIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	44887
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2508542248
Incident Name	NAPP2508542248 RED TANK 30 WTR TREATMENT FAC @ 0
Incident Type	Produced Water Release
Incident Status	Notification Accepted

Location of Release Source		
Site Name	RED TANK 30 WTR TREATMENT FAC	
Date Release Discovered	03/24/2025	
Surface Owner	State	

Liner Inspection Event Information			
Please answer all the questions in this group.			
What is the liner inspection surface area in square feet	23,243		
Have all the impacted materials been removed from the liner	No		
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	04/09/2025		
Time liner inspection will commence	09:00 AM		
Please provide any information necessary for observers to liner inspection	Omar Martinez (575) 343-7858		
Please provide any information necessary for navigation to liner inspection site	32.35942753 , -103.6125464		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 448887

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	448887
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By		Condition Date
wdittrich	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	4/4/2025