****** LIQUID SPILLS - VOLUME CALCULATIONS ******

Location of spill:	Rana Salada 0605 Fed Com 202H	Date of Spill:
		Site Soil Type:

Average Daily Production: BBL Oil BBL Water

	Tota	l Area Calcul	ations			
Total Surface Area	width		length		wet soil depth	oil (%)
Rectangle Area #1	56 ft	Х	100 ft	Х	1 in	100%
Rectangle Area #2	0 ft	X	0 ft	X	0 in	0%
Rectangle Area #3	O ft	X	O ft	Χ	0 in	0%
Rectangle Area #4	O ft	X	O ft	Χ	0 in	0%
Rectangle Area #5	O ft	X	O ft	Χ	0 in	0%
Rectangle Area #6	O ft	X	O ft	Χ	0 in	0%
Rectangle Area #7	O ft	X	O ft	Χ	0 in	0%
Rectangle Area #8	0 ft	X	0 ft	X	0 in	0%
_						

Porosity <u>0.16</u> gal per gal

Saturated	Soil Volume Calculations:			
		<u>H2O</u>	<u>OIL</u>	
Area #1	5600 sq. ft.	cu. ft.	467	cu. ft.
Area #2	0 sq. ft.	cu. ft.		cu. ft.
Area #3	0 sq. ft.	cu. ft.		cu. ft.
Area #4	0 sq. ft.	cu. ft.		cu. ft.
Area #5	0 sq. ft.	cu. ft.		cu. ft.
Area #6	0 sq. ft.	cu. ft.		cu. ft.
Area #7	0 sq. ft.	cu. ft.		cu. ft.
Area #8	0 sq. ft.	cu. ft.		cu. ft.
Total Solid/Liquid Volume:	5,600 sq. ft.	cu. ft.	467	cu. ft.
<u>Estimate</u>	d Volumes Spilled			
		<u>H2O</u>	<u>OIL</u>	
Liqu	id in Soil:	0.0 BBL	13.3	BBL
Liquid Re	covered :	<u>0.0</u> <u>BBL</u>	0.0	<u>BBL</u>
S	pill Liquid	0.0 BBL	13.3	BBL
Total Sp	pill Liquid:	13.3	3	
Page	vored Valumas			
Estimated oil recovered:	vered Volumes 0.0 BBL			
Estimated water recovered:	0.0 BBL			

Soil Type	Porosity	
Clay	0.15	
Peat	0.40	
Glacial Sediments	0.13	
Sandy Clay	0.12	
Silt	0.16	
Loess	0.25	
Fine Sand	0.16	
Medium Sand	0.25	
Coarse Sand	0.26	
Gravely Sand	0.26	
Fine Gravel	0.26	
Medium Gravel	0.25	
Coarse Gravel	0.18	
Sandstone	0.25	
Siltstone	0.18	
Shale	0.05	
Limestone	0.13	
Basalt	0.19	
Volcanic Tuff	0.20	
Standing Liquids		

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 451779

QUESTIONS

	Operator:	OGRID:
Permian Resources Operating, LLC		372165
	300 N. Marienfeld St Ste 1000	Action Number:
	Midland, TX 79701	451779
		Action Type:
		[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites			
Incident ID (n#)	nAPP2510453210		
Incident Name	NAPP2510453210 RANA SALADA 0605 FED COM 202H @ 0		
Incident Type	Other		
Incident Status	Initial C-141 Received		

Location of Release Source			
Please answer all the questions in this group.			
Site Name	Rana Salada 0605 Fed Com 202H		
Date Release Discovered	04/14/2025		
Surface Owner	Federal		

Incident Details			
Please answer all the questions in this group.			
Incident Type	Other		
Did this release result in a fire or is the result of a fire	No		
Did this release result in any injuries	No		
Has this release reached or does it have a reasonable probability of reaching a watercourse	No		
Has this release endangered or does it have a reasonable probability of endangering public health	No		
Has this release substantially damaged or will it substantially damage property or the environment	No		
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No		

Nature and Volume of Release				
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.				
Crude Oil Released (bbls) Details	Not answered.			
Produced Water Released (bbls) Details	Not answered.			
Is the concentration of chloride in the produced water >10,000 mg/l	No			
Condensate Released (bbls) Details	Cause: Power Failure Pump Condensate Released: 13 BBL Recovered: 0 BBL Lost: 13 BBL.			
Natural Gas Vented (Mcf) Details	Not answered.			
Natural Gas Flared (Mcf) Details	Not answered.			
Other Released Details	Not answered.			
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Not answered.			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 451779

QUESTIONS	(continued)
QUEUTION	(COI IUI IU C U)

Q02011	orto (continuou)
Operator: Permian Resources Operating, LLC	OGRID: 372165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	451779
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)
QUESTIONS	[O-141] Illidal O-141 (O-141-V-Illidal)
Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	
	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	No
Reasons why this would be considered a submission for a notification of a major release	Unavailable.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e.	e. gas only) are to be submitted on the C-129 form.
Initial Response	
The responsible party must undertake the following actions immediately unless they could create a s	rafety hazard that would result in injury
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the	Tito
environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed	
appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.
Per Paragraph (4) of Subsection R of 19 15 29 8 NMAC the responsible party may commence remedia	 ation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative
	ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of
	·
	knowledge and understand that pursuant to OCD rules and regulations all operators are required ases which may endanger public health or the environment. The acceptance of a C-141 report by
the OCD does not relieve the operator of liability should their operations have failed to a	adequately investigate and remediate contamination that pose a threat to groundwater, surface
water, human health or the environment. In addition, OCD acceptance of a C-141 repor local laws and/or regulations.	t does not relieve the operator of responsibility for compliance with any other federal, state, or
	Name: Matthew Taylor
I hereby agree and sign off to the above statement	Title: Environmental Coordinator
	Email: matthew.taylor@permianres.com Date: 04/14/2025
1	Dato. 01/11/2020

Sante Fe Main Office Phone: (505) 476-3441 General Information

storage site

Phone: (505) 629-6116 Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 451779

QUESTIONS (continued)

Operator:	OGRID:
Permian Resources Operating, LLC	372165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	451779
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS Site Characterization Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the What is the shallowest depth to groundwater beneath the area affected by the Not answered. release in feet below ground surface (ft bgs) What method was used to determine the depth to ground water Not answered. Did this release impact groundwater or surface water Not answered What is the minimum distance, between the closest lateral extents of the release and the following surface areas: A continuously flowing watercourse or any other significant watercourse Not answered Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) Not answered. An occupied permanent residence, school, hospital, institution, or church Not answered. A spring or a private domestic fresh water well used by less than five households Not answered. for domestic or stock watering purposes Any other fresh water well or spring Not answered. Incorporated municipal boundaries or a defined municipal fresh water well field Not answered. Not answered. A subsurface mine Not answered. An (non-karst) unstable area Not answered. Categorize the risk of this well / site being in a karst geology A 100-year floodplain Not answered. Did the release impact areas not on an exploration, development, production, or Not answered.

Remediation Plan				
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.				
Requesting a remediation plan approval with this submission	No			
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has similar at the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.				

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 451779

CONDITIONS

Operator:	OGRID:
Permian Resources Operating, LLC	372165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	451779
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By		Condition Date
rhamlet	None	4/15/2025