Monthly Meter Analysis April 2025

Meter #: T234040981

Name: TREBLE CTB SEPARATOR 3

Sample

Date:

Type:

Pressure: 200.0 H2O: Temperature: 60.0 H2S:

Component	Mole %	Liquid Content	Mass %
Carbon Dioxide (CO2)	2.7066		5.3810
Nitrogen (N2)	2.1641		2.7386
Methane (C1)	73.9760		53.6113
Ethane (C2)	11.3709	3.0279	15.4457
Propane (C3)	6.0230	1.6522	11.9979
Isobutane (IC4)	0.7887	0.2570	2.0708
n-Butane (NC4)	1.7953	0.5636	4.7140
Isopentane (IC5)	0.4451	0.1621	1.4506
n-Pentane (NC5)	0.3999	0.1443	1.3033
Hexanes Plus (C6+) Argon (Ar) Carbon Monoxide (CO) Hydrogen (H2) Oxygen (O2) Helium (He) Water (H2O) Hydrogen Sulfide (H2S)	0.3305	0.1353	1.2868
Totals	100.0001	5.9424	100.0000


	Total
Property	Sample
Pressure Base	14.650
Temperature Base	60.00
Relative Density	0.7668
HV, Dry @ Base P,T	1234.44
HV, Sat @ Base P, T	1212.96
HV, Sat @ Sample P, T	1232.86
Cricondentherm	
HCDP @ Sample Pressure	
Full Wellstream	
Free Water	
Condensate	
26 # RVP Gasoline	0.643
Testcar Permian	0.657
Testcar Panhandle	0.614
Testcar Midcon	0.584

*** End of Report ***



Coterra Energy Inc.
Corporate Headquarters
Three Memorial City Plaza
840 Gessner Road
Suite 1400
Houston, TX 77024

T 281-589-4600 F 281-589-4955 coterra.com



Intermediate flaring:

Event Date	Volume Flowed (mcf)	Duration (hrs)
4/30/2025	527	0.00

Details:

[331501] NORTHWIND MIDSTREAM PARTNERS LLC, Gas Quality Issue - Non-H2S, PURGING O2

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

DEFINITIONS

Action 462344

DEFINITIONS

Operator:	OGRID:
Franklin Mountain Energy 3, LLC	331595
6001 Deauville Blvd.	Action Number:
Midland, TX 79706	462344
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 462344

Ql	UESTIONS	
Operator:		OGRID:
Franklin Mountain Energy 3, LLC 6001 Deauville Blvd.		331595 Action Number:
Midland, TX 79706		462344
		Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve t	hese issues before continuing wit	h the rest of the questions.
Incident Well	Unavailable.	
Incident Facility	[fAPP2314257355] Treble	СТВ
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers an	nd may provide addional quidance	
Was this vent or flare caused by an emergency or malfunction	No	
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No	
Is this considered a submission for a vent or flare event	Yes, major venting and/or	flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during very was there at least 50 MCF of natural gas vented and/or flared during this event		be a major or minor release under 19.15.29.7 NMAC.
	Yes	
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group. Methane (CH4) percentage	74	
	2	
Nitrogen (N2) percentage, if greater than one percent		
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	3	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required speci	ifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	

Not answered.

Oxygen (02) percentage quality requirement

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 462344

QUESTI	ONS (continued)
Operator:	OGRID:
Franklin Mountain Energy 3, LLC	331595
6001 Deauville Blvd. Midland, TX 79706	Action Number: 462344
malana, 17.10100	Action Type:
	[C-129] Venting and/or Flaring (C-129)
QUESTIONS	
Date(s) and Time(s)	
Date vent or flare was discovered or commenced	04/30/2025
Time vent or flare was discovered or commenced	12:00 AM
Time vent or flare was terminated	12:00 AM
Cumulative hours during this event	0
Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Separator Natural Gas Flared Released: 527 Mcf Recovered: 0 Mcf Lost: 527 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.
Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	Mo
Was notification of downstream activity received by this operator	No Not answered.
Downstream OGRID that should have notified this operator	****
	Not answered.
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare	Not answered.
Time notined of downstream activity requiring this vent of hare	Not answered.
Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	vrus off due to high O2
Steps taken to limit the duration and magnitude of vent or flare	MINIMIZE EVENT DURATION
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	PURGING O2

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 462344

ACKNOWLEDGMENTS

Operator:	OGRID:
Franklin Mountain Energy 3, LLC	331595
6001 Deauville Blvd.	Action Number:
Midland, TX 79706	462344
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

V	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
V	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
V	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 462344

CONDITIONS

Operator:	OGRID:
Franklin Mountain Energy 3, LLC	331595
6001 Deauville Blvd.	Action Number:
Midland, TX 79706	462344
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By		Condition Date
jressling	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	5/14/2025