

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

QUESTIONS

Action 482373

QUESTIONS

|   |  |
|---|--|
| Operator:<br><br>XTO ENERGY, INC<br>6401 Holiday Hill Road<br>Midland, TX 79707 | OGRID:<br><br>5380   |
|   | Action Number:<br><br>482373   |
|   | Action Type:<br><br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

QUESTIONS

|                   |  |
|-------------------|--|
| Prerequisites     |  |
| Incident ID (n#)  | nAPP2514157393                         |
| Incident Name     | NAPP2514157393 CORRAL CANYON 8 SAT @ 0 |
| Incident Type     | Produced Water Release                 |
| Incident Status   | Initial C-141 Approved                 |
| Incident Facility | [fAPP2207552359] CORRAL CANYON 8 SAT   |

|                            |                     |
|----------------------------|---------------------|
| Location of Release Source |                     |
| Site Name                  | CORRAL CANYON 8 SAT |
| Date Release Discovered    | 05/20/2025          |
| Surface Owner              | Federal             |

|   |  |
|---|--|
| Liner Inspection Event Information  |  |
| Please answer all the questions in this group.  |  |
| What is the liner inspection surface area in square feet  | 140  |
| Have all the impacted materials been removed from the liner   | Yes  |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 07/08/2025   |
| Time liner inspection will commence   | 09:00 AM   |
| Warning: Notification can not be less than two business days prior to conducting liner inspection.      |  |
| Please provide any information necessary for observers to liner inspection                              | Tracy Hillard - 575-937-3906   |
| Please provide any information necessary for navigation to liner inspection site                        | GPS: 32.142756, -104.006845. Open Access, potential H2S and livestock. |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 482373

CONDITIONS

|   |  |
|---|--|
| Operator:<br><br>XTO ENERGY, INC<br>6401 Holiday Hill Road<br>Midland, TX 79707 | OGRID:<br><br>5380   |
|   | Action Number:<br><br>482373   |
|   | Action Type:<br><br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Created By | Condition  | Condition Date |
|------------|--|----------------|
| thillard   | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 7/7/2025       |