Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 496840

## **QUESTIONS**

ı	Operator:	OGRID:
ı	XTO ENERGY, INC	5380
ı	6401 Holiday Hill Road	Action Number:
ı	Midland, TX 79707	496840
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

## QUESTIONS

Prerequisites			
Incident ID (n#)	nAPP2434134681		
Incident Name	NAPP2434134681 PLU BIG SINKS 19 24 31 USA BATTERY @ 0		
Incident Type	Produced Water Release		
Incident Status	Initial C-141 Approved		
Incident Facility	[fAPP2123046724] BIG SINKS 19 24 31 USA 1Y		

Location of Release Source		
Site Name	PLU BIG SINKS 19 24 31 USA BATTERY	
Date Release Discovered	12/05/2024	
Surface Owner	Federal	

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	3,700			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	08/20/2025			
Time liner inspection will commence	02:00 PM			
Please provide any information necessary for observers to liner inspection	Tracy Hillard; THillard@ensolum.com			
Please provide any information necessary for navigation to liner inspection site	GPS: 32.21004, -103.81949. Open Access, Potential H2S and livestock			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 496840

## **CONDITIONS**

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	496840
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

## CONDITIONS

Created By		Condition Date
thillard	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	8/18/2025