Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 496617

QUESTIONS

| ı | Operator: | OGRID: |
|---|-------------------------------------|--|
| ı | DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| ı | 333 West Sheridan Ave. | Action Number: |
| ı | Oklahoma City, OK 73102 | 496617 |
| ı | | Action Type: |
| ı | | [NOTIFY] Notification Of Liner Inspection (C-141L) |

QUESTIONS

| Prerequisites | S | |
|-------------------|---|--|
| Incident ID (n#) | nAPP2516154121 | |
| Incident Name | NAPP2516154121 RAGIN CAJUN 12 CTB 3 @ 0 | |
| Incident Type | Produced Water Release | |
| Incident Status | Initial C-141 Approved | |
| Incident Facility | [fAPP2423338309] RAGIN CAJUN 12 CTB 3 | |

| Location of Release Source | |
|----------------------------|----------------------|
| Site Name | RAGIN CAJUN 12 CTB 3 |
| Date Release Discovered | 06/09/2025 |
| Surface Owner | Federal |

| Liner Inspection Event Information | | |
|---|------------------------|--|
| ease answer all the questions in this group. | | |
| What is the liner inspection surface area in square feet | 4,100 | |
| Have all the impacted materials been removed from the liner | Yes | |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 08/22/2025 | |
| Time liner inspection will commence | 10:30 AM | |
| Please provide any information necessary for observers to liner inspection | Monica Peppin | |
| Please provide any information necessary for navigation to liner inspection site | 32.061330, -103.419596 | |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 496617

CONDITIONS

| Operator: | OGRID: |
|-------------------------------------|--|
| DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| 333 West Sheridan Ave. | Action Number: |
| Oklahoma City, OK 73102 | 496617 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Create By | | Condition Date |
|--------------|--|-------------------|
| jrale | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 8/18/2025 |