Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 497922

QUESTIONS

Operator:		OGRID:	
ı	Spur Energy Partners LLC	328947	
ı	9655 Katy Freeway	Action Number:	
ı	Houston, TX 77024	497922	
ı		Action Type:	
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)	

QUESTIONS

Prerequisites	isites		
Incident ID (n#)	nAPP2518131216		
Incident Name	NAPP2518131216 SKELLY UNIT #605 BATTERY @ 0		
Incident Type	Oil Release		
Incident Status	Initial C-141 Approved		

ocation of Release Source	
Site Name	SKELLY UNIT #605 BATTERY
Date Release Discovered	06/28/2025
Surface Owner	Private

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	11,500			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	08/25/2025			
Time liner inspection will commence	08:30 AM			
Please provide any information necessary for observers to liner inspection	Andrew Franco 806-200-0054			
Please provide any information necessary for navigation to liner inspection site	32.833741,-103.839199			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 497922

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	497922
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Creat By	d Condition	Condition Date
pim	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	8/20/2025