Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 507595

QUESTIONS

Operator:	OGRID:
CIMAREX ENERGY CO. OF COLORADO	162683
6001 Deauville Blvd	Action Number:
Midland, TX 79706	507595
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2512052637	
Incident Name	NAPP2512052637 MADURO NORTH FEDERAL 4H @ 30-025-39998	
Incident Type	Produced Water Release	
Incident Status	Initial C-141 Approved	
Incident Well	[30-025-39998] NORTH MADURO FEDERAL UNIT #004H	
Incident Facility	[fAPP2202546495] MADURO NORTH FED 4H	

Location of Release Source	
Site Name	MADURO NORTH FEDERAL 4H
Date Release Discovered	04/29/2025
Surface Owner	Federal

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	2,400			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	09/24/2025			
Time liner inspection will commence	12:30 PM			
Please provide any information necessary for observers to liner inspection	Laci Luig - 432-208-3035			
Please provide any information necessary for navigation to liner inspection site	32.65122,-103.69252			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 507595

CONDITIONS

Operator:	OGRID:
CIMAREX ENERGY CO. OF COLORADO	162683
6001 Deauville Blvd	Action Number:
Midland, TX 79706	507595
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created	By Condition	Condition Date
athiel	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	9/19/2025