


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

3004509278

OPERATOR

x Initial Report

Final Report

Name of Company: Devon Energy Production Co. L.P.	Contact ☐ Mr. Steve Zink, Production Foreman
Address: 3300 N. Butler, Suite 211, Farmington, NM 87401	Telephone No. ☐ (505) 324-0033
Facility Name: NEBU 103	Facility Type: Well site
Surface Owner: Bureau of Reclamation	Mineral Owner: Bureau of Land Management
Lease No. ☐ SF 078615	

LOCATION OF RELEASE

Unit Letter N	Section 24	Township 30N	Range 08W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
-------------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------------

NATURE OF RELEASE

Type of Release: 2% KCL Water	Volume of Release ~8 bbls	Volume Recovered ☐ 0 bbls
Source of Release: Reserve pit	Date and Hour of Occurrence 08/15/02 12:00 PM	Date and Hour of Discovery ☐ 8/15/02 12:00 PM
Was Immediate Notice Given? Not Required ☒ Yes (within 24 hrs) ☐ No ☐	If YES, To Whom? Denny Foust, New Mexico Oil Conserv. (505) 334-6718 x15.	
By Whom? ☐ Kenny Rhoades Devon Energy	Date and Hour ☐ 8/15/02 1:00 PM	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* Spill was confined to a dry drainage approximately 1200' from location and 1 mile from Navajo Dam Reservoir		
Describe Cause of Problem and Remedial Action Taken.* Crew was cleaning out well into small reserve pit that was lined and fenced. Well unloaded and overfilled pit resulting in ~8 bbls 2% KCL water spilling over onto ground. Approximately 3 bbls ended up in dry sand wash below location running ~ 1200' from location in a path ~ 2' wide.		
Describe Area Affected and Cleanup Action Taken.* An area approximately 1200 ft ² downgradient of the well site received fluid. A crew was called to location and built a land farm on location that will be maintained by Devon Energy representatives. The crew then cleaned up all contaminated soil and put in land farm.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Steve Zink	Approved by ☐ District Supervisor: For Frank Chavez	
Title: Production Foreman	Approval Date: 8/29/02	Expiration Date:
Date: August 16, 2002 Phone: (505) 324-0033	Conditions of Approval:	Attached ☐

* Attach Additional Sheets If Necessary

NDGFO222833656

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 520453

CONDITIONS

Operator: DEVON ENERGY OPERATING CORP 20 N Broadway Oklahoma City, OK 73102	OGRID: 136025
	Action Number: 520453
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
nvez	None	10/28/2025