Epic Energy South Blanco Federal 25 #8,9,10 Tank Battery Unit K, Section 25, Township 24 North, Range 8 West Facility ID fAPP2203258231 Incident #nAPP2529633728 San Juan County, New Mexico

SPILL CALCULATION

The approximate extent of the contamination is 32,860 square feet.

The **tank** that overtopped originally had 117 bbls of oil. The hydrovac'd fluids were returned to the tank and recorded at 40 bbls for a net loss of 77 bbls. An unknown volume of frac fluid was released; however, approximately 300 bbls was recovered during hydrovac activities.

The depth of vertical contamination is unknown at this time.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 524310

QUESTIONS

Operator:	OGRID:
EPIC ENERGY, L.L.C.	372834
332 Road 3100	Action Number:
Aztec, NM 87410	524310
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2529633728
Incident Name	NAPP2529633728 SOUTH BLANCO FEDERAL 25 #8,9,10 TB @ FAPP2203258231
Incident Type	Oil Release
Incident Status	Initial C-141 Received
Incident Facility	[fAPP2203258231] South Blanco Federal 25 #8, 9, 10 TB

Location of Release Source	
Please answer all the questions in this group.	
Site Name	South Blanco Federal 25 #8,9,10 TB
Date Release Discovered	10/22/2025
Surface Owner	Federal

ncident Details	
lease answer all the questions in this group.	
Incident Type	Oil Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	Yes
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release		
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.		
Crude Oil Released (bbls) Details	Cause: Overflow - Tank, Pit, Etc. Production Tank Crude Oil Released: 117 BBL Recovered: 40 BBL Lost: 77 BBL.	
Produced Water Released (bbls) Details	Not answered.	
Is the concentration of chloride in the produced water >10,000 mg/l	No	
Condensate Released (bbls) Details	Not answered.	
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Not answered.	
Other Released Details	Not answered.	
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Stimulation activities at the nearby Enduring Resources well caused the AST at the Tank Battery to overflow and release the tank contents and an unknown volume of frac fluid, however, approximately 300 bbls was recovered during hydrovac activities. The release extended beyond the secondary containment, across the roadway, and into a field adjacent to the tank battery. The cause of the release is a direct result of the stimulation activities that extended beyond the notification period with no update provided to the operator.	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 524310

31.1.1.	,
QUESTI	ONS (continued)
Operator:	OGRID:
EPIC ENERGY, L.L.C. 332 Road 3100	372834
Aztec, NM 87410	Action Number: 524310
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)
QUESTIONS	
Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more; (2) an unauthorized release of a volume that: (d) substantially damages property or the environment.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e.	e. gas only) are to be submitted on the C-129 form.
Initial Response	
The responsible party must undertake the following actions immediately unless they could create a s	
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.
	ation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of valuation in the follow-up C-141 submission.
to report and/or file certain release notifications and perform corrective actions for releating the OCD does not relieve the operator of liability should their operations have failed to a	knowledge and understand that pursuant to OCD rules and regulations all operators are require ases which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface t does not relieve the operator of responsibility for compliance with any other federal, state, or
I hereby agree and sign off to the above statement	Name: Shawna Martinez Title: Regulatory Technician Email: shawna@walsheng.net Date: 41/47/2025

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 3

Action 524310

QUESTIONS (continued)

Operator:	OGRID:
EPIC ENERGY, L.L.C.	372834
332 Road 3100	Action Number:
Aztec, NM 87410	524310
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS Site Characterization Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the What is the shallowest depth to groundwater beneath the area affected by the Not answered. release in feet below ground surface (ft bgs) What method was used to determine the depth to ground water Not answered. Did this release impact groundwater or surface water Not answered What is the minimum distance, between the closest lateral extents of the release and the following surface areas: A continuously flowing watercourse or any other significant watercourse Not answered Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) Not answered. An occupied permanent residence, school, hospital, institution, or church Not answered. A spring or a private domestic fresh water well used by less than five households Not answered. for domestic or stock watering purposes Any other fresh water well or spring Not answered. Incorporated municipal boundaries or a defined municipal fresh water well field Not answered. Not answered. A subsurface mine Not answered. An (non-karst) unstable area Not answered. Categorize the risk of this well / site being in a karst geology A 100-year floodplain Not answered. Did the release impact areas not on an exploration, development, production, or Not answered. storage site

Remediation Plan		
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.		
Requesting a remediation plan approval with this submission	No	
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 524310

CONDITIONS

Operator:	OGRID:
EPIC ENERGY, L.L.C.	372834
332 Road 3100	Action Number:
Aztec, NM 87410	524310
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created B	V Condition	Condition Date
rhamlet	None	11/18/2025